
Uncontained engine failure, Douglas DC-9-32, May 5, 1994

Micro-summary: This Douglas DC-9-32 had an uncontained engine failure of the #1 engine.


Event Date: 1994-05-05 at 0855 CDT

Investigative Body: National Transportation Safety Board (NTSB), USA

Investigative Body's Web Site: <http://www.nts.gov/>

Cautions:

1. Accident reports can be and sometimes are revised. Be sure to consult the investigative agency for the latest version before basing anything significant on content (e.g., thesis, research, etc).
 2. Readers are advised that each report is a glimpse of events at specific points in time. While broad themes permeate the causal events leading up to crashes, and we can learn from those, the specific regulatory and technological environments can and do change. ***Your company's flight operations manual is the final authority as to the safe operation of your aircraft!***
 3. Reports may or may not represent reality. Many many non-scientific factors go into an investigation, including the magnitude of the event, the experience of the investigator, the political climate, relationship with the regulatory authority, technological and recovery capabilities, etc. It is recommended that the reader review all reports analytically. Even a "bad" report can be a very useful launching point for learning.
 4. Contact us before reproducing or redistributing a report from this anthology. Individual countries have very differing views on copyright! We can advise you on the steps to follow.
-

		NTSB ID: ATL94IA097		Aircraft Registration Number: N986US	
		Occurrence Date: 05/05/1994		Most Critical Injury: None	
		Occurrence Type: Incident		Investigated By: NTSB	
Location/Time					
Nearest City/Place MEMPHIS		State TN	Zip Code 38116	Local Time 0855	Time Zone CDT
Airport Proximity: On Airport		Distance From Landing Facility:		Direction From Airport:	
Aircraft Information Summary					
Aircraft Manufacturer DOUGLAS		Model/Series DC-9-32		Type of Aircraft Airplane	
Sightseeing Flight: No			Air Medical Transport Flight: No		
Narrative					
Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:					
<p>On May 5, 1994, about 0855 central daylight time, a Douglas DC-9-32, N986US, had an uncontained engine failure during the takeoff roll at Memphis, Tennessee. Flight 661 was operated by Northwest Airlines under Title 14 Code of Federal Regulations (CFR) Part 121 as a scheduled, domestic, passenger flight. Visual meteorological conditions prevailed. An instrument flight rules flight plan was filed for the flight to Phoenix, Arizona. There were no injuries to the airline transport pilots, the three flight attendants, nor the 64 passengers; and minor damage to the airplane. The flight was originating at the time of the accident.</p> <p>During the takeoff roll, approximately 125 knots, the flight crew heard a loud explosion and noted that all of the left engine instruments were reducing to zero indication. The takeoff was rejected, and the engine shut down. The engine fire extinguisher was discharged. As the airplane was taxied onto a taxiway, tower personnel informed the flight crew that smoke was coming from the engine. The flight crew obtained information from fire/rescue personnel and determined that an evacuation was not required.</p> <p>A post incident examination of the engine, which was installed in left position of N986US, showed that an uncontained failure of the combustion case had occurred. The engine cowling was partially opened up and distorted. There was minor shrapnel damage to an unpressurized portion of the fuselage, adjacent to the engine. The engine, a Pratt and Whitney JT8D-15, serial number 657510, was removed to the Northwest Airlines engine overhaul facility in Atlanta, Georgia, for additional visual examination. The combustion chamber outer case (CCOC) had fractured through a bolt hole of the rear flange, at the engine's three o'clock position. All of the combustion cans were in place and there was no evidence of an external fire. The outer case opened along an axial plane with the upper and lower halves displacing up and down, respectively, as if opening a briefcase. The fracture surface on the lower portion of the case was discolored black from the rear flange bolt hole forward about four inches. Its coloration then changed to red for about 3.75 to 4.00 inches. The fracture surface then abruptly changed to a lighter color (bronze then steel) for about five inches. Subsequently, the engine was forwarded to Pratt and Whitney facilities for in-depth examination. A metallurgical examination was conducted by Pratt and Whitney which revealed that the fracture resulted from low cycle fatigue in the separated bolt hole, of the rear flange. Low cycle fatigue cracks were observed in numerous additional bolt holes. The case material conformed to composition and hardness requirements.</p> <p>Rear flange fractures of the CCOC are the subject of Federal Aviation Administration Airworthiness Directive 87-10-01 R1, effective November 13, 1989, and Pratt and Whitney Alert Service Bulletin 5676 dated July 15, 1986. The incident engine had been inspected in accordance with both documents on November 28, 1990. The combustion case had 5,940 cycles since the inspection, and had 2,060 cycles remaining until the required inspection was again due at 8,000 cycles.</p>					
FACTUAL REPORT - AVIATION					
Page 1					

National Transportation Safety Board

FACTUAL REPORT

AVIATION

SAFETY BOARDS

NTSB ID: ATL94IA097


Occurrence Date: 05/05/1994


Occurrence Type: Incident

Narrative (Continued)

Two previous CCOC fractures have occurred, similar to the fracture in this incident. The first occurred during takeoff and the second occurred during routine reassembly following engine maintenance. An All Operator's Wire was issued by Pratt and Whitney, following the second fracture occurrence. The wire discussed a "low toughness condition" of older cases that, under certain conditions, could result in an intergranular crack.

Following the additional examinations of the engine, Pratt and Whitney, in conjunction with the Federal Aviation Administration, are pursuing the issuance of inspections to preclude similar, undetected CCOC cracks.

 National Transportation Safety Board FACTUAL REPORT AVIATION		NTSB ID: ATL94IA097			
		Occurrence Date: 05/05/1994			
		Occurrence Type: Incident			
Landing Facility/Approach Information					
Airport Name	Airport ID:	Airport Elevation	Runway Used	Runway Length	Runway Width
MEMPHIS INTERNATIONAL	MEM	352 Ft. MSL	36L	9319	150
Runway Surface Type: Concrete					
Runway Surface Condition: Dry					
Type Instrument Approach: NONE					
VFR Approach/Landing: None					
Aircraft Information					
Aircraft Manufacturer		Model/Series		Serial Number	
DOUGLAS		DC-9-32		47480	
Airworthiness Certificate(s): Transport					
Landing Gear Type: Retractable - Tricycle					
Homebuilt Aircraft? No	Number of Seats: 104	Certified Max Gross Wt.	108000 LBS	Number of Engines: 3	
Engine Type:	Engine Manufacturer:	Model/Series:	Rated Power:		
Turbo Fan	P&W	JT8D-15	15000 LBS		
- Aircraft Inspection Information					
Type of Last Inspection	Date of Last Inspection	Time Since Last Inspection	Airframe Total Time		
Continuous Airworthiness	04/1994	37 Hours	54685 Hours		
- Emergency Locator Transmitter (ELT) Information					
ELT Installed? No	ELT Operated?	ELT Aided in Locating Accident Site?			
Owner/Operator Information					
Registered Aircraft Owner		Street Address			
FIRST SECURITY BANKS OF UTAH		City		State	Zip Code
		SALT LAKE CITY		UT	
Operator of Aircraft		Street Address			
NORTHWEST AIRLINES, INC		5101 NORTHWEST DRIVE			
		City		State	Zip Code
		ST. PAUL		MN	55111
Operator Does Business As:			Operator Designator Code: NWAA		
- Type of U.S. Certificate(s) Held:					
Air Carrier Operating Certificate(s): Flag Carrier/Domestic					
Operating Certificate:			Operator Certificate:		
Regulation Flight Conducted Under: Part 121: Air Carrier					
Type of Flight Operation Conducted: Scheduled; Domestic; Passenger Only					

 <p>National Transportation Safety Board FACTUAL REPORT AVIATION</p>	NTSB ID: ATL94IA097
	Occurrence Date: 05/05/1994
	Occurrence Type: Incident

First Pilot Information

Name On File	City On File	State On File	Date of Birth On File	Age 49
-----------------	-----------------	------------------	--------------------------	-----------

Sex: M	Seat Occupied: Left	Principal Profession: Civilian Pilot	Certificate Number: On File
--------	---------------------	--------------------------------------	-----------------------------

Certificate(s): Airline Transport

Airplane Rating(s): Multi-engine Land

Rotorcraft/Glider/LTA: None

Instrument Rating(s): Airplane

Instructor Rating(s): Airplane Single-engine; None

Type Rating/Endorsement for Accident/Incident Aircraft? Yes	Current Biennial Flight Review?
---	---------------------------------

Medical Cert.: Class 1	Medical Cert. Status: Valid Medical--no waivers/lim.	Date of Last Medical Exam: 02/1994
------------------------	--	------------------------------------

- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Multi-Engine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	19657	4266								
Pilot In Command(PIC)										
Instructor										
Last 90 Days	198	198		198						
Last 30 Days	83	83		83						
Last 24 Hours	7	7		7						

Seatbelt Used? Yes	Shoulder Harness Used? Yes	Toxicology Performed? No	Second Pilot? Yes
--------------------	----------------------------	--------------------------	-------------------

Flight Plan/Itinerary

Type of Flight Plan Filed: IFR

Departure Point Same as Accident/Incident Location	State	Airport Identifier	Departure Time 0840	Time Zone CDT
---	-------	--------------------	------------------------	------------------

Destination PHOENIX	State AZ	Airport Identifier PHX	
------------------------	-------------	---------------------------	--


Type of Clearance: IFR

Type of Airspace: Class D; Class E

Weather Information

Source of Briefing: Commercial Weather Service; Flight Service Station; PATWAS

Method of Briefing:

 <p>National Transportation Safety Board FACTUAL REPORT AVIATION</p>	NTSB ID: ATL94IA097
	Occurrence Date: 05/05/1994
	Occurrence Type: Incident

Weather Information					
WOF ID	Observation Time	Time Zone	WOF Elevation	WOF Distance From Accident Site	Direction From Accident Site
MEM	0855	CDT	352 Ft. MSL	1 NM	180 Deg. Mag.
Sky/Lowest Cloud Condition: Clear			0 Ft. AGL	Condition of Light: Day	
Lowest Ceiling: None		0 Ft. AGL		Visibility: 10 SM	Altimeter: 30.00 "Hg
Temperature: 16 °C	Dew Point: °C	Wind Direction:		Density Altitude: Ft.	
Wind Speed: Calm	Gusts:	Weather Conditions at Accident Site: Visual Conditions			
Visibility (RVR): 0 Ft.	Visibility (RVV) 0 SM	Intensity of Precipitation: Unknown			
Restrictions to Visibility: None					
Type of Precipitation: None					

Accident Information		
Aircraft Damage: Minor	Aircraft Fire: None	Aircraft Explosion: None

Classification: U.S. Registered/U.S. Soil					
- Injury Summary Matrix	Fatal	Serious	Minor	None	TOTAL
First Pilot				1	1
Second Pilot				1	1
Student Pilot					
Flight Instructor					
Check Pilot					
Flight Engineer					
Cabin Attendants				3	3
Other Crew					
Passengers				64	64
- TOTAL ABOARD -				69	69
Other Ground	0	0	0		0
- GRAND TOTAL -	0	0	0	69	69

National Transportation Safety Board

FACTUAL REPORT

AVIATION



NTSB ID: ATL94IA097

Occurrence Date: 05/05/1994

Occurrence Type: Incident

Administrative Information

Investigator-In-Charge (IIC)

PRESTON E. HICKS,

Additional Persons Participating in This Accident/Incident Investigation:

JEROME FRECHETTE
NTSB
WASHINGTON, DC

JOE EPPERSON
NTSB
WASHINGTON, DC

F. K PORTER
MEMPHIS, TN FSDO
MEMPHIS, TN