

---

## Uncontained engine failure, Boeing 757, January 31, 1997

---

**Micro-summary:** This Boeing 757 experienced an uncontained engine failure of the #1 engine during climb.

---

**Event Date:** 1997-01-31 at 1610 EST


**Investigative Body:** National Transportation Safety Board (NTSB), USA

**Investigative Body's Web Site:** <http://www.nts.gov/>

---

### **Cautions:**

1. Accident reports can be and sometimes are revised. Be sure to consult the investigative agency for the latest version before basing anything significant on content (e.g., thesis, research, etc).
  2. Readers are advised that each report is a glimpse of events at specific points in time. While broad themes permeate the causal events leading up to crashes, and we can learn from those, the specific regulatory and technological environments can and do change. ***Your company's flight operations manual is the final authority as to the safe operation of your aircraft!***
  3. Reports may or may not represent reality. Many many non-scientific factors go into an investigation, including the magnitude of the event, the experience of the investigator, the political climate, relationship with the regulatory authority, technological and recovery capabilities, etc. It is recommended that the reader review all reports analytically. Even a "bad" report can be a very useful launching point for learning.
  4. Contact us before reproducing or redistributing a report from this anthology. Individual countries have very differing views on copyright! We can advise you on the steps to follow.
-

		NTSB ID: ATL97IA035		Aircraft Registration Number: N611DL	
		Occurrence Date: 01/31/1997		Most Critical Injury: None	
		Occurrence Type: Incident		Investigated By: NTSB	
Location/Time					
Nearest City/Place ATLANTA		State GA	Zip Code 30320	Local Time 1610	Time Zone EST
Airport Proximity: Off Airport/Airstrip		Distance From Landing Facility: 35		Direction From Airport: 270	
Aircraft Information Summary					
Aircraft Manufacturer Boeing		Model/Series 757-232		Type of Aircraft Airplane	
Sightseeing Flight: No			Air Medical Transport Flight: No		
Narrative					
Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:					
<p>On January 31, 1997, about 1610 eastern standard time, a Boeing 757, N611DL, experienced an uncontained failure of the number one (left) engine during climb, near Atlanta, Georgia. The airplane, Flight 602, was operated by Delta Air Lines under instrument flight rules, and the provisions of Title 14 CFR Part 121, as a scheduled, domestic, passenger flight. An instrument flight plan was activated. Visual meteorological conditions prevailed. There were no injuries to the two flight crewmembers, the five flight attendants, and the 161 passengers, and the airplane incurred minor damage. Origination of the flight was Atlanta, Georgia, about 1600 on the same day. The flight was destined for Dallas, Texas.</p> <p>According the captain, the airplane was climbing through about 15,000 feet when "the engine failed abruptly". The cockpit and aft cabin filled partially with smoke which cleared quickly. The captain requested an immediate return to Atlanta's William B. Hartsfield International Airport. The landing was uneventful. After being visually inspected for fire, the airplane was able to taxi back to the gate without further incident.</p> <p>The left engine was a Pratt and Whitney PW2037 turbofan, serial number 716582. Delta's records indicate the engine had accumulated 19,243 hours total time and 9,823 cycles since new. The engine had operated 3,518 hours and 1,719 cycles since its last heavy maintenance visit on September 26, 1996.</p> <p>An examination by Delta, Pratt and Whitney, and the Powerplants Group of the National Transportation Safety Board revealed the Stage 1 high pressure turbine (HPT) disk, Part Number 1B3621, had fractured and was missing the lug between two blade root slots. According to the report by the Powerplants Group, this rupture liberated one Stage 1 lug and two Stage 1 HPT blades. One blade was recovered from the cowling and determined to be "battered and fractured transversely across the airfoil adjacent to the blade root platform".</p> <p>A visual examination showed the fracture surface was "smooth and had a purple discoloration from the front side that faded to a gold color towards the rear" of the disk. According to the Powerplants Group report, the "fir tree serrations on the adjacent lugs were intact." At the time of separation, according to Delta's records, the Stage 1 HPT disk had accumulated 9,825 cycles since new, and 1,719 cycles since the last heavy maintenance. Part Number 1B3621 Stage 1 HPT disks are life limited to 15,000 cycles.</p> <p>The remaining rotating parts of the HPT were intact, with impact damage on the blades. The low pressure turbine (LPT) was intact. Its vanes and blades both had "nicks and dents". The remainder of the engine appeared normal and was not disassembled.</p> <p>A metallurgical examination was completed by Pratt and Whitney's material laboratory in February, 1997. The examination showed that the "HPT disk blade retention lug had separated</p>					
FACTUAL REPORT - AVIATION					
Page 1					

National Transportation Safety Board

**FACTUAL REPORT**

**AVIATION**

SAFETY BOARD

NTSB ID: ATL97IA035

Occurrence Date: 01/31/1997


Occurrence Type: Incident


**Narrative** (Continued)

because of a low cycle fatigue (LCF) fracture that had initiated from multiple origins along the front sideplate snap radius and propagated axially rearward. The origins of the fatigue fracture were parallel to circumferential machining marks that were just inboard of the snap radius".

After this and other similar HPT failures, Pratt and Whitney produced an Alert Service Bulletin (ASB). This bulletin, PW2000 A72-592, described a modification of the HPT disk assembly for all PW2037, PW2037(M), PW2040, PW2240, and PW2337 engines. This Service Bulletin attempted to prevent further blade attachment lug liberations by enlarging the front and rear sideplate snap radii. This modification was designed to reduce the stresses and eliminate the cracking in the radii which was allowing the blades to be liberated.

From Pratt and Whitney's Alert Service Bulletin, the FAA produced a Telegraphic Airworthiness Directive (TAD) 97-11-51T, which required serviceable disks to be operated in accordance with Pratt and Whitney's ASB No. PW2000 A72-592.

 <b>National Transportation Safety Board</b> <b>FACTUAL REPORT</b> <b>AVIATION</b>		NTSB ID: ATL971A035			
		Occurrence Date: 01/31/1997			
		Occurrence Type: Incident			
<b>Landing Facility/Approach Information</b>					
Airport Name	Airport ID:	Airport Elevation	Runway Used	Runway Length	Runway Width
HARTSFIELD INTERNATIONAL	ATL	1026 Ft. MSL	27L	11889	150
Runway Surface Type: Concrete					
Runway Surface Condition: Dry					
Type Instrument Approach: NONE					
VFR Approach/Landing: Precautionary Landing					
<b>Aircraft Information</b>					
Aircraft Manufacturer		Model/Series		Serial Number	
Boeing		757-232		22818	
Airworthiness Certificate(s): Transport					
Landing Gear Type: Retractable - Tricycle					
Homebuilt Aircraft? No	Number of Seats: 190	Certified Max Gross Wt.	223800 LBS	Number of Engines: 2	
Engine Type:	Engine Manufacturer:	Model/Series:	Rated Power:		
Turbo Fan	P&W	PW2037	37530 LBS		
- Aircraft Inspection Information					
Type of Last Inspection	Date of Last Inspection	Time Since Last Inspection	Airframe Total Time		
Continuous Airworthiness	01/1997	106 Hours	37395 Hours		
- Emergency Locator Transmitter (ELT) Information					
ELT Installed? No	ELT Operated?	ELT Aided in Locating Accident Site?			
<b>Owner/Operator Information</b>					
Registered Aircraft Owner		Street Address			
DELTA AIR LINES		1020 DELTA BLVD			
		City	State	Zip Code	
		ATLANTA	GA	30320	
Operator of Aircraft		Street Address			
Same as Reg'd Aircraft Owner		Same as Reg'd Aircraft Owner			
		City	State	Zip Code	
Operator Does Business As:			Operator Designator Code: DALA		
- Type of U.S. Certificate(s) Held:					
Air Carrier Operating Certificate(s): Flag Carrier/Domestic					
Operating Certificate:			Operator Certificate:		
Regulation Flight Conducted Under: Part 121: Air Carrier					
Type of Flight Operation Conducted: Scheduled; Domestic; Passenger Only					

 <p><b>National Transportation Safety Board</b> <b>FACTUAL REPORT</b> <b>AVIATION</b></p>	NTSB ID: ATL97IA035
	Occurrence Date: 01/31/1997
	Occurrence Type: Incident

**First Pilot Information**

Name On File	City On File	State On File	Date of Birth On File	Age 58
-----------------	-----------------	------------------	--------------------------	-----------

Sex: M	Seat Occupied: Left	Principal Profession: Civilian Pilot	Certificate Number: On File
--------	---------------------	--------------------------------------	-----------------------------

Certificate(s): Airline Transport

Airplane Rating(s): Multi-engine Land

Rotorcraft/Glider/LTA: None

Instrument Rating(s): Airplane

Instructor Rating(s): None

Type Rating/Endorsement for Accident/Incident Aircraft? Yes	Current Biennial Flight Review?
---	---------------------------------

Medical Cert.: Class 1	Medical Cert. Status: Valid Medical--no waivers/lim.	Date of Last Medical Exam: 11/1996
------------------------	--	------------------------------------

- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Multi-Engine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	15000	2751								
Pilot In Command(PIC)										
Instructor										
Last 90 Days	225	225								
Last 30 Days										
Last 24 Hours										

Seatbelt Used? Yes	Shoulder Harness Used? Yes	Toxicology Performed? No	Second Pilot? Yes
--------------------	----------------------------	--------------------------	-------------------

**Flight Plan/Itinerary**

Type of Flight Plan Filed: IFR

Departure Point Same as Accident/Incident Location	State	Airport Identifier ATL	Departure Time 1600	Time Zone EST
---	-------	---------------------------	------------------------	------------------

Destination DALLAS	State TX	Airport Identifier DFW	
-----------------------	-------------	---------------------------	--


Type of Clearance: IFR

Type of Airspace: Class B

**Weather Information**

Source of Briefing:  
Company

Method of Briefing:

 <p>National Transportation Safety Board <b>FACTUAL REPORT</b> AVIATION</p>	NTSB ID: ATL97IA035
	Occurrence Date: 01/31/1997
	Occurrence Type: Incident

<b>Weather Information</b>					
WOF ID	Observation Time	Time Zone	WOF Elevation	WOF Distance From Accident Site	Direction From Accident Site
ATL	1556	EDT	1026 Ft. MSL	35 NM	270 Deg. Mag.
Sky/Lowest Cloud Condition: Unknown			0 Ft. AGL	Condition of Light: Day	
Lowest Ceiling: Broken		25000 Ft. AGL		Visibility: 10 SM	Altimeter: 29.00 "Hg
Temperature: 15 °C	Dew Point: -1 °C	Wind Direction: 260		Density Altitude: 1200 Ft.	
Wind Speed: 11	Gusts: 15	Weather Conditions at Accident Site: Visual Conditions			
Visibility (RVR): 0 Ft.	Visibility (RVV) 0 SM	Intensity of Precipitation: Unknown			
Restrictions to Visibility: None					
Type of Precipitation: None					

<b>Accident Information</b>		
Aircraft Damage: Minor	Aircraft Fire: None	Aircraft Explosion: None

Classification: U.S. Registered/U.S. Soil					
<b>- Injury Summary Matrix</b>	Fatal	Serious	Minor	None	TOTAL
First Pilot				1	1
Second Pilot				1	1
Student Pilot					
Flight Instructor					
Check Pilot					
Flight Engineer					
Cabin Attendants				5	5
Other Crew					
Passengers				161	161
- TOTAL ABOARD -				168	168
Other Ground	0	0	0		0
- GRAND TOTAL -	0	0	0	168	168

--	--	--	--	--	--

National Transportation Safety Board

**FACTUAL REPORT**

**AVIATION**



NTSB ID: ATL97IA035

Occurrence Date: 01/31/1997

Occurrence Type: Incident

Administrative Information

Investigator-In-Charge (IIC)

PRESTON E. HICKS

Additional Persons Participating in This Accident/Incident Investigation:

FRAN DEJOSEPH

GEORGIA FSDO

REGAN H CAMPBELL

NTSB-ATLANTA OFFICE