## Tail strike on landing, McDonnell Douglas MD-11, November 11, 1998

Micro-summary: An FMS error resulted in this McDonnell Douglas MD-11 flying a too-slow approach, resulting in a tailstrike.

Event Date: 1998-11-11 at 1120 PST

Investigative Body: National Transportation Safety Board (NTSB), USA

Investigative Body's Web Site: http://www.ntsb.gov/

## **Cautions:**

- 1. Accident reports can be and sometimes are revised. Be sure to consult the investigative agency for the latest version before basing anything significant on content (e.g., thesis, research, etc).
- 2. Readers are advised that each report is a glimpse of events at specific points in time. While broad themes permeate the causal events leading up to crashes, and we can learn from those, the specific regulatory and technological environments can and do change. Your company's flight operations manual is the final authority as to the safe operation of your aircraft!
- 3. Reports may or may not represent reality. Many many non-scientific factors go into an investigation, including the magnitude of the event, the experience of the investigator, the political climate, relationship with the regulatory authority, technological and recovery capabilities, etc. It is recommended that the reader review all reports analytically. Even a "bad" report can be a very useful launching point for learning.
- 4. Contact us before reproducing or redistributing a report from this anthology. Individual countries have very differing views on copyright! We can advise you on the steps to follow.

Aircraft Accident Reports on DVD, Copyright © 2006 by Flight Simulation Systems, LLC All rights reserved.

www.fss.aero

National Transportation Safety Board	1	NTSB ID:	SEA99LA01	4	Aircraft Regist	Aircraft Registration Number: N801DE				
FACTUAL REPORT		Occurrence	e Date: 11/11	1/1998	Most Critical I	Most Critical Injury: None				
AVIATION	(	Occurrence	e Type: Accid	lent	Investigated E	Investigated By: NTSB				
Location/Time										
Nearest City/Place	State Zip		Code	Local Time	Time Zone					
PORTLAND	OR	97	218	1120	PST					
Airport Proximity: On Airport	Distanc	e From La	nding Facility:	Direction Fro	Direction From Airport:					
Aircraft Information Summary										
Aircraft Manufacturer		Model/Series	3		Type of Aircraft					
McDonnell Douglas		MD-11		Airplane						
Sightseeing Flight: No	Ai	ir Medical Transport Flight: No								

## Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On November 11, 1998, at 1120 Pacific standard time, a McDonnell Douglas MD-11, N801DE, operated by Delta Air Lines as a 14 CFR Part 121 scheduled passenger flight, experienced a tail strike while landing at Portland International Airport, Portland, Oregon. The flight was landing on runway 10R after arriving from Cincinnati, Ohio. Visual meteorological conditions prevailed, and an instrument flight plan had been filed. There were no injuries to the 11 crew members or 113 passengers, but the aircraft sustained substantial damage to the belly skin and stringers.

The flight crew stated that they were unaware the aircraft had experienced a tail strike until maintenance personnel at the arrival gate advised them that there was damage to the number 3 VHF antenna and the skin aft of the antenna mount. After the passengers were deplaned normally through the jetway, the damage was further evaluated, and it was determined that the aircraft would need to be ferried to Atlanta for permanent repair.

During the investigation, it was determined that the weight existing in the Flight Management System (FMS) during the approach and landing sequence was in error approximately 100,000 pounds. As confirmed by a review of the Flight Data Recorder (FDR) readout, the FMS weight was about 292,000 pounds, when in fact the actual aircraft landing weight was approximately 392,000 pounds. This error generated a final approach speed of 136 knots for an approach that should have been flown at 151 knots. This reduced speed resulted in the approach being flown at an eight (8) degree pitch attitude instead of the three to four degrees that would occur during an approach flown at the correct airspeed. The FDR data also showed that approximately 7 seconds before nose gear strut compression, the pitch attitude reached 10.9 degrees. According to the operator, while landing at this speed and attitude "... tail clearance tolerances are minimal."

Although the exact FMS entry error was not determined, the most likely would be the crew missing the hundred thousand entry by one when inputting the takeoff gross weight, entering the empty weight into the zero fuel weight prompt, or entering the zero fuel weight in the aircraft takeoff gross weight prompt.

According to the operator, as a result of the lessons learned from this accident, Delta Air Lines is putting additional emphasis on the MD-11 FMS loading procedures during flight training and line checks. In addition, Delta is implementing a program that stresses awareness of proper pitch attitude while in the final approach mode.

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: SEA99LA014

Occurrence Date: 11/11/1998

AVIATION	ccurrence Type: Accident												
Landing Facility/Approach Info	rmation												
Airport Name			Airport I	D:	Airport Eleva	tion	Run	way Used	sed Runway Length			Runv	vay Width
PORTLAND INTERNATIONAL			PDX		20 Ft.	MSL	10F	₹	1100	0		150	
Runway Surface Type: Concrete													
Runway Surface Condition: Dry													
Type Instrument Approach: Visual													
VFR Approach/Landing: Full Stop													
Aircraft Information													
Aircraft Manufacturer McDonnell Douglas		odel/S ID-11	eries					Serial 4856	Numbe	er			
Airworthiness Certificate(s): Transp													
7 mworumiooo oorumoato(o). Tranop													
Landing Gear Type: Retractable - Tricycle													
Homebuilt Aircraft? No	Number of Seats: 2	262	Certified Max Gross Wt.					625000 LBS Number			er of Engines: 2		: 2
=			Engine Manufacturer: Model/Series: P&W 4460						Rated Power: 60000 LBS				
- Aircraft Inspection Information													
Type of Last Inspection			Date of Last Inspection Time Sir				nce Last Insp	ection	Airfran	ne To	tal Time		
Continuous Airworthiness			11/1999 5 Hou						ours	ours 24332 Hours			
- Emergency Locator Transmitter (E	LT) Information												
ELT Installed? No	ELT Operate	ed?				ELT	Aided ii	n Locating A	ccident S	Site?			
Owner/Operator Information													
Registered Aircraft Owner			Street Address HARTSFIELD INTERNATIONAL ARPT.										
DELTA AIR LINES, INC.			City								Stat	е	Zip Code
			Stre	et Ado	ATLANT	<u> </u>					GA		30320
Operator of Aircraft			Same as Reg'd Aircraft Owner										
Same as Reg'd Aircraft Owner			City								Stat	е	Zip Code
Operator Does Business As: DELTA	•				Op	perator Desig	gnator Co	ode: DA	LΑ				
- Type of U.S. Certificate(s) Held:													
Air Carrier Operating Certificate(s): F	-lag Carrier/Dom	nestic											
Operating Certificate:					Operator C	Certific	ate:						
Regulation Flight Conducted Under:	Part 121: Air Ca	rrier											
Type of Flight Operation Conducted:	Scheduled; Don	nestic;	Passer	nger (	Only								
	]	FACTU	UAL RE	EPOR	T - AVIATI	ON							Page 2

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: SEA99LA014

Occurrence Date: 11/11/1998

AVIATION	Occurrence Type: Accident												
First Pilot Information													
Name					City					Stat	:e	Date of Birth	Age
On File					On File	ile On File On File						On File	56
Sex: M Seat Occupied: I	Left	Prin	cipal Profes	sion: Civilia	n Pilot				Cer	tificate	e Numb	er: On File	
Certificate(s): Airline					·								
Airplane Rating(s): Multi-engine Land; Single-engine Land													
Rotorcraft/Glider/LTA: Helicopter													
Instrument Rating(s): Airplane													
Instructor Rating(s): None													
Type Rating/Endorsement for Accident/Incident Aircraft? Yes  Current Biennial Flight Review?													
Medical Cert.: Class 1 Medical Cert. Status: Valid Medicalw/ waivers								[	Date of La	ast Me	edical E	xam: 07/1998	
	•												
- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Nigh	ht Instrument Actual S		ent Simulated	Rotorcraf		Glider	Lighter Than Air	
Total Time	10000	4082				Acteur							
Pilot In Command(PIC)													
Instructor					-					$\perp$			
Last 90 Days		241								_			
Last 30 Days		0								+			
Last 24 Hours  Seatbelt Used? Yes	01	8	1110 W		1.	Tavias	ology De		ad0 NI=			econd Pilot? Ye	_
Seatbelt Used? Yes	Snou	lder Harness	Used? Yes			TOXICC	Diogy Pe	HIOIII	ed? No		36	econd Pilot? Ye	<u></u>
Flight Plan/Itinerary													
Type of Flight Plan Filed: IFR	?												
Departure Point	•				Т	State	Ī	Airport Identifier			Depar	Time Zone	
CINCINNATI						ОН		CVG			Departure Time 0940		CST
Destination						State		Airpor	t Identifie	r			
Same as Accident/Inciden	nt Location					State Airport Identif PDX		r raoritino					
Type of Clearance: IFR													
Type of Airspace: Class D	)												
Weather Information													
Source of Briefing: Compar	ny												
Method of Briefing:													
			FACTUAL	REPORT	- AVIA	TION	٧						Page 3

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: SEA99LA014

Occurrence Date: 11/11/1998

Occurrence Type: Accident

	PETYBOR			unchec i	урс.	Acciden									
Weather	Information														
WOF ID	Observation Time	Time Zone	WOF E	Elevation		WOF Distance From Accident Site					Direction From	m Accident S	Site		
KPD	1156	PST		20 Ft. MS	0 Ft. MSL				1 NM		0 Deg. Mag.		g. Mag.		
Sky/Lowes	st Cloud Condition: Scatt	ered		3500 Ft. AGL					Condition of Light: Day						
Lowest Ce	iling: Broken	650	00 Ft. AG	iL	Visibil	lity:	10	SM	Alti	meter:	30.00	"Hg			
Temperatu	ıre: 8 °C [	Dew Point:	6	o°C V	Nind [	Direction:	140			Dei	nsity Altitude:		Ft.		
Wind Spee	ed: 4	Gusts:		Weather Condtions at Accident Site: Visual Conditions											
Visibility (R	RVR): 0 Ft.	Visibility	y (RVV)	0 S	SM	Intensity	of Precipita	ation: (	Jnknown						
Restriction	s to Visibility: None														
Type of Pre	ecipitation: None														
Accident	Information														
Aircraft Dar	mage: Substantial		Aircra	Aircraft Fire: None					Aircraft Expl	losio	n None				
Classificati	ion: U.S. Registered/U.	.S. Soil													
- Injury Sur	mmary Matrix	Fatal	Serious	Minor	T	None	TOTAL								
First Pil	lot				$oxed{oxed}$	1	1								
Second	d Pilot					1	1								
Student	t Pilot				T										
Flight Ir	nstructor				T										
Check F	Pilot														
Flight E	Engineer				$\top$										
Cabin A	Attendants				$\top$	9	9								
Other C	Crew				T										
Passen	ngers				十	113	113								
- TOTAL A	ABOARD -				十	124	124								
Other G	Ground	0	0		0		0								
- GRAND	O TOTAL -	0	0		0	124	124								

National Transportation Safety Board

FACTUAL REPORT AVIATION NTSB ID: SEA99LA014

Occurrence Date: 11/11/1998

Occurrence Type: Accident

Αc	lmi	inis	trativ	⁄e In	for	matior	۱

Investigator-In-Charge (IIC)

ORRIN K. ANDERSON

Additional Persons Participating in This Accident/Incident Investigation:

RON HOLLOWAY PORTLAND FSDO HILLSBORO, OR