
Contained engine failure, Douglas DC-9-82, June 25, 1999

Micro-summary: Contained engine failure concomitant with rotation for this DC-9-82.


Event Date: 1999-06-25 at 1440 PDT

Investigative Body: National Transportation Safety Board (NTSB), USA

Investigative Body's Web Site: <http://www.nts.gov/>

Cautions:

1. Accident reports can be and sometimes are revised. Be sure to consult the investigative agency for the latest version before basing anything significant on content (e.g., thesis, research, etc).
 2. Readers are advised that each report is a glimpse of events at specific points in time. While broad themes permeate the causal events leading up to crashes, and we can learn from those, the specific regulatory and technological environments can and do change. ***Your company's flight operations manual is the final authority as to the safe operation of your aircraft!***
 3. Reports may or may not represent reality. Many many non-scientific factors go into an investigation, including the magnitude of the event, the experience of the investigator, the political climate, relationship with the regulatory authority, technological and recovery capabilities, etc. It is recommended that the reader review all reports analytically. Even a "bad" report can be a very useful launching point for learning.
 4. Contact us before reproducing or redistributing a report from this anthology. Individual countries have very differing views on copyright! We can advise you on the steps to follow.
-

		NTSB ID: LAX99IA230		Aircraft Registration Number: N450AA	
		Occurrence Date: 06/25/1999		Most Critical Injury: None	
		Occurrence Type: Incident		Investigated By: NTSB	
Location/Time					
Nearest City/Place SAN DIEGO		State CA	Zip Code 92145	Local Time 1440	Time Zone PDT
Airport Proximity: On Airport		Distance From Landing Facility:		Direction From Airport:	
Aircraft Information Summary					
Aircraft Manufacturer Boeing		Model/Series DC-9-82		Type of Aircraft Airplane	
Sightseeing Flight: No			Air Medical Transport Flight: No		
Narrative					
Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:					
<p>On June 25, 1999, about 1440 hours Pacific daylight time, American Airlines Flight 2090, a Boeing DC-9-82 (MD-82), N450AA, experienced a contained engine failure during departure from Lindbergh Field, San Diego, California. American Airlines operated the airplane as a scheduled domestic passenger flight to Dallas-Fort Worth, Texas, under the provisions of 14 CFR Part 121. The airline transport pilot licensed captain, first officer, 4 cabin attendants, and 135 passengers were not injured. The airplane was on an instrument flight rules (IFR) flight plan and was not damaged. Visual meteorological conditions prevailed.</p> <p>The flight crew reported that they heard a pop after the nose wheel lifted up during rotation on takeoff. The airplane pulled to the right as they lost power on the right engine. They did not notice any alarms or caution lights. They stated they performed required checklists and secured the engine. An emergency was declared and an uneventful landing was completed at the Miramar Marine Corps Air Station, San Diego. All passengers deplaned normally by the airplane's stairs. A preliminary visual inspection determined that all of the blades were missing from the last stage of the turbine. Damage was also observed on the next stage forward. No damage was apparent to the compressor section.</p> <p>A detailed examination of the engine was performed at American Airlines maintenance facility in Tulsa, Oklahoma, and observed by a Federal Aviation Administration (FAA) inspector. The FAA inspector noted the engine was a Pratt & Whitney JT8D-217C, serial number 725576. He reported that a review of records disclosed that the time on the engine since its installation on this airplane, which coincided with time since its last shop visit, was 3,980 hours.</p> <p>Teardown of the engine revealed that all third and fourth stage turbine blades fractured at the root and no fatigue marks were noted. The second-stage turbine blades fractured at 1/2 to 2/3 span. All low-pressure turbine nozzle guide vanes exhibited leading edge rub and meshed with adjacent turbine blade trailing edges. The turbine case bulged in several areas. The inspector noted the turbine exhaust case and number 6 bearing support exhibited damage consistent with aft movement of the low-pressure turbine. The high-pressure compressor drive shaft exhibited minor damage and all three antirotational pins were present. The low-pressure compressor drive turbine shaft fractured approximately 25 inches aft of the low-pressure compressor end. This was at a point relative to the plane of the 12th stage high-pressure compressor disk and the forward portion of the rear compressor seal tube. This fracture twisted and contained a large area of displaced and galled metal; coke/carbon was observed under the galled metal.</p> <p>The number 4 1/2 bearing oil supply manifold assembly was in good condition with all three oil packings in place and intact. The number three bearing was damaged. All balls were worn with flat spots that were up to 1/2 the ball circumference. Spalling was evident on the inner and outer race, but no race spinning was evident. The cage was intact, but worn. No evidence of oil starvation or overheating was observed.</p>					
FACTUAL REPORT - AVIATION					
					Page 1

National Transportation Safety Board

FACTUAL REPORT

AVIATION

SAFETY BOARD

NTSB ID: LAX99IA230

Occurrence Date: 06/25/1999


Occurrence Type: Incident


Narrative (Continued)

A flow check of the oil supply system to the number three bearing was completed with no blockage or flow anomalies detected.

Metallurgical examination by an independent laboratory could not determine a cause for the bearing failure.

The FAA inspector noted that the number three bearing had accumulated 12,487 hours and the low-pressure compressor drive shaft accumulated 27,230 hours since new. An American Airlines representative reported that compressor washes were not specified in the maintenance manual for this engine series. A representative for the engine manufacturer noted that the coke/carbon buildup was not in the gas path, therefore, compressor washes would not remove this buildup. He opined this buildup was from burning oil that leaked into a hot area after the bearing failure.

 National Transportation Safety Board FACTUAL REPORT AVIATION		NTSB ID: LAX991A230			
		Occurrence Date: 06/25/1999			
		Occurrence Type: Incident			
Landing Facility/Approach Information					
Airport Name LINDBERG FIELD	Airport ID: SAN	Airport Elevation 14 Ft. MSL	Runway Used 27	Runway Length 9400	Runway Width 200
Runway Surface Type: Concrete					
Runway Surface Condition: Dry					
Type Instrument Approach: NONE					
VFR Approach/Landing: Precautionary Landing					
Aircraft Information					
Aircraft Manufacturer Boeing		Model/Series DC-9-82		Serial Number 49476	
Airworthiness Certificate(s): Transport					
Landing Gear Type: Retractable - Tricycle					
Homebuilt Aircraft? No	Number of Seats: 145	Certified Max Gross Wt. 149500 LBS	Number of Engines: 2		
Engine Type: Turbo Jet	Engine Manufacturer: P&W	Model/Series: JT8D-217C	Rated Power: 21000 LBS		
- Aircraft Inspection Information					
Type of Last Inspection Continuous Airworthiness	Date of Last Inspection	Time Since Last Inspection Hours	Airframe Total Time 34641 Hours		
- Emergency Locator Transmitter (ELT) Information					
ELT Installed? Yes	ELT Operated? No	ELT Aided in Locating Accident Site?			
Owner/Operator Information					
Registered Aircraft Owner AMERICAN AIRLINES		Street Address 4333 AMON CARTER BLVD			
		City FORT WORTH	State TX	Zip Code 76155	
Operator of Aircraft WILMINGTON TRUST CO		Street Address RODNEY SQUARE NORTH			
		City WILMINGTON	State DE	Zip Code 19890	
Operator Does Business As:			Operator Designator Code: AALA		
- Type of U.S. Certificate(s) Held:					
Air Carrier Operating Certificate(s): Flag Carrier/Domestic					
Operating Certificate:			Operator Certificate:		
Regulation Flight Conducted Under: Part 121: Air Carrier					
Type of Flight Operation Conducted: Scheduled; Domestic; Passenger Only					

 <p>National Transportation Safety Board FACTUAL REPORT AVIATION</p>	NTSB ID: LAX99IA230
	Occurrence Date: 06/25/1999
	Occurrence Type: Incident

First Pilot Information

Name On File	City On File	State On File	Date of Birth On File	Age 42
-----------------	-----------------	------------------	--------------------------	-----------

Sex: M	Seat Occupied: Left	Principal Profession: Civilian Pilot	Certificate Number: On File
--------	---------------------	--------------------------------------	-----------------------------

Certificate(s): Airline Transport; Commercial

Airplane Rating(s): Multi-engine Land; Single-engine Land; Single-engine Sea

Rotorcraft/Glider/LTA: None

Instrument Rating(s): Airplane

Instructor Rating(s): Airplane Single-engine

Type Rating/Endorsement for Accident/Incident Aircraft? Yes	Current Biennial Flight Review?
---	---------------------------------

Medical Cert.: Class 1	Medical Cert. Status: Valid Medical--no waivers/lim.	Date of Last Medical Exam: 03/1999
------------------------	--	------------------------------------

- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Multi-Engine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	8000									
Pilot In Command(PIC)										
Instructor										
Last 90 Days										
Last 30 Days										
Last 24 Hours										

Seatbelt Used? Yes	Shoulder Harness Used? Yes	Toxicology Performed? No	Second Pilot? Yes
--------------------	----------------------------	--------------------------	-------------------

Flight Plan/Itinerary

Type of Flight Plan Filed: IFR

Departure Point SAN DIEGO	State CA	Airport Identifier SAN	Departure Time 1410	Time Zone PDT
------------------------------	-------------	---------------------------	------------------------	------------------

Destination DALLAS	State TX	Airport Identifier DFW	
-----------------------	-------------	---------------------------	--


Type of Clearance: IFR

Type of Airspace: Class B

Weather Information

Source of Briefing: Company

Method of Briefing:

 <p>National Transportation Safety Board FACTUAL REPORT AVIATION</p>	NTSB ID: LAX99IA230
	Occurrence Date: 06/25/1999
	Occurrence Type: Incident

Weather Information					
WOF ID	Observation Time	Time Zone	WOF Elevation	WOF Distance From Accident Site	Direction From Accident Site
NKX	1456	PDT	478 Ft. MSL	0 NM	0 Deg. Mag.
Sky/Lowest Cloud Condition: Clear			0 Ft. AGL	Condition of Light: Day	
Lowest Ceiling: None		0 Ft. AGL		Visibility: 10 SM	Altimeter: 29.00 "Hg
Temperature: 22 °C	Dew Point: 14 °C	Wind Direction: 330		Density Altitude: Ft.	
Wind Speed: 7	Gusts:	Weather Conditions at Accident Site: Visual Conditions			
Visibility (RVR): 0 Ft.	Visibility (RVV) 0 SM	Intensity of Precipitation: Unknown			
Restrictions to Visibility: None					
Type of Precipitation: None					

Accident Information		
Aircraft Damage: None	Aircraft Fire: None	Aircraft Explosion: None

Classification: U.S. Registered/U.S. Soil					
- Injury Summary Matrix	Fatal	Serious	Minor	None	TOTAL
First Pilot				1	1
Second Pilot				1	1
Student Pilot					
Flight Instructor					
Check Pilot					
Flight Engineer					
Cabin Attendants				4	4
Other Crew					
Passengers				135	135
- TOTAL ABOARD -				141	141
Other Ground	0	0	0		0
- GRAND TOTAL -	0	0	0	141	141

--	--

National Transportation Safety Board

FACTUAL REPORT

AVIATION



NTSB ID: LAX99IA230

Occurrence Date: 06/25/1999

Occurrence Type: Incident

Administrative Information

Investigator-In-Charge (IIC)

HOWARD D. PLAGENS

Additional Persons Participating in This Accident/Incident Investigation:

JOHN WINFORD
WP-SAN-FSDO
SAN DIEGO, CA 92123

KARL YOUNG
FAA
FORT WORTH, TX 75261