## Ground collision between a Douglas DC-8 and DC-10, December 17, 1999

Micro-summary: This Douglas DC-8 collided with a parked McDonnell Douglas DC-10 while taxiing.

Event Date: 1999-12-17 at 1604 CST

Investigative Body: National Transportation Safety Board (NTSB), USA

Investigative Body's Web Site: http://www.ntsb.gov/

## **Cautions:**

- 1. Accident reports can be and sometimes are revised. Be sure to consult the investigative agency for the latest version before basing anything significant on content (e.g., thesis, research, etc).
- 2. Readers are advised that each report is a glimpse of events at specific points in time. While broad themes permeate the causal events leading up to crashes, and we can learn from those, the specific regulatory and technological environments can and do change. Your company's flight operations manual is the final authority as to the safe operation of your aircraft!
- 3. Reports may or may not represent reality. Many many non-scientific factors go into an investigation, including the magnitude of the event, the experience of the investigator, the political climate, relationship with the regulatory authority, technological and recovery capabilities, etc. It is recommended that the reader review all reports analytically. Even a "bad" report can be a very useful launching point for learning.
- 4. Contact us before reproducing or redistributing a report from this anthology. Individual countries have very differing views on copyright! We can advise you on the steps to follow.

Aircraft Accident Reports on DVD, Copyright © 2006 by Flight Simulation Systems, LLC All rights reserved.

www.fss.aero

National Transportation Safety Board	N <sup>-</sup>	TSB ID:	CHI00LA047	7	Aircraft Registi	Aircraft Registration Number: N995CF  Most Critical Injury: None				
FACTUAL REPORT	00	ccurrence	e Date: 12/17	7/1999	Most Critical Ir					
AVIATION	O	ccurrence	е Туре: Ассіс	lent	Investigated B	Investigated By: NTSB				
Location/Time										
Nearest City/Place	State	Zip	Code Local Time		Time Zone					
INDIANAPOLIS	IN	462	241	1604	CST					
Airport Proximity: On Airport	roximity: On Airport Distance From				Direction Fro	Direction From Airport:				
Aircraft Information Summary										
Aircraft Manufacturer			Model/Series	3		Type of Aircraft				
Douglas		DC-8-62		Airplane						
Sightseeing Flight: No	Aiı	r Medical Tr	ansport Flight: No							

## Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On December 17, 1999, at 1604 central standard time, a McDonnell Douglas DC-8-62, N995CF, operated by Emery Worldwide Airlines as Flight #638, collided with a parked, Gemini DC-10, while taxing on the United States Postal Service (USPS) Eagle Hub Ramp at the Indianapolis International Airport, Indianapolis, Indiana. The captain, first officer, and flight engineer were not injured. The airplane received substantial damage. The 14 CFR Part 121 cargo flight was originating at the time of the accident. Visual meteorological conditions prevailed and an IFR flight plan was filed.

Prior to taxiing, N995CF was parked in spot B4C. The DC-10 was parked in spot C2C. The captain reported they received their taxi clearance from Evergreen and they began to taxi from the parking spot with the assistance of a marshaller. (Evergreen Aviation Ground Logistics Enterprises, Inc., is under contract with the United States Postal Service to provide ramp control and ground handling on the Eagle Hub Ramp.) He stated they were directed to taxi forward then turn left and follow the green taxi line. The captain stated that after making the left turn, they were lined up on the yellow and black taxi line. He stated he corrected toward the green line, but felt that being on the green line would bring them too close to other aircraft parked on their left side. It was during the turn to align with the green taxi line that the right wing struck the radome of the parked DC-10. The captain reported, "Since there were no 'follow me' truck or wing walkers we had to keep diligence on the a/c wing tips ourselves."

The first officer reported, "We were taxied forward past the green-dashed lines as well as the solid yellow taxi line. The marshaller then gave us a left turn and released us to taxi on our own." He stated the captain, "...found the green dashed line to the left of the yellow taxi line and was attempting to taxi to the line when our aircraft's right wing tip struck the parked DC- 10 at which point we stopped and shut down."

The right wingtip, outboard wing rib and spar cap, sheet metal, wingtip lights and static wicks were damaged on N995CF. The radome, pitot tube, and an antenna on the parked DC-10 were also damaged.

C-Net operations were in affect on the Eagle Hub Ramp at the time of the accident. Emery Worldwide Airlines offered the following description of C-Net operations.

"The majority of Eagle Hub operations occur during the night with mostly B-727 sized aircraft. During the Christmas season, the USPS conducts a two week long C-Net operation during the daylight hours involving up to 40 aircraft, including multiple DC-8s, B-747s, DC-10s, and MD-11s. Because of the large number and size of the aircraft, the normal Eagle Hub Ramp aircraft parking and taxi routes are modified to support C-Net aircraft operations."

"During normal Eagle Hub operations, the taxi lines used between the parking rows are solid black and yellow lines. For the C-Net operations, taxi lines between several of the parking rows

National Transportation Safety Board
FACTUAL REPORT

NTSB ID: CHI00LA047

Occurrence Date: 12/17/1999

Occurrence Type: Accident

Narrative (Continued)

are temporarily moved to accommodate the larger aircraft and were painted dashed green lines. Depending on the parking spot, the aircraft would be directed by the Eagle Hub Ramp controller to follow either the normal black/yellow line or the temporary dashed green lines."

Following this accident Evergreen Aviation Ground Logistics Enterprises, Inc., changed their operating procedures during C- Net operations at the Indianapolis International Airport. The new procedures are as follows: "One marshaller will startup the aircraft, check the surrounding area for hazards and signal the aircraft out of the block spot to the correct taxi line. The marshaller will then hand off the flight to the second marshaller. The second marshaller will position himself well ahead of the aircraft on the taxi line, thus directing the aircraft through the aircraft that may be on either side. The aircraft will then be released to proceed under ground control."

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: CHI00LA047

Occurrence Date: 12/17/1999

AVIATION		Occurrence Type: Accident											
Landing Facility/Approach In	formation	•											
Airport Name			Airport ID:	Airport Eleva	tion	Run	way Used	Runwa	y Lengt	:h	Runv	vay Width	
INDIANAPOLIS INT'L		IND	797 Ft										
Runway Surface Type:													
Runway Surface Condition:													
Type Instrument Approach:													
VFR Approach/Landing:													
Aircraft Information													
Aircraft Manufacturer Douglas			Mode DC-8	I/Series 3-62					Serial 4602		Number 4		
Airworthiness Certificate(s): Trans													
Landing Gear Type: Retractable - Tricycle													
Homebuilt Aircraft? No	Number of Seats:	7	Certifie	ed Max Gross V	335000 LBS Number			er of Engines: 2		: 2			
				Engine Manufacturer: Model/Series: JT3D-7							Rate	d Power:	
- Aircraft Inspection Information													
Type of Last Inspection Da				st Inspection	nce Last Inspection			Airfrar	ne To	tal Time			
Continuous Airworthiness 1			12/1999	12/1999 0 Hou						urs 63922 Hours			
- Emergency Locator Transmitter (ELT) Information													
ELT Installed?	stalled? ELT Operated?					Aided in	n Locating Ac	cident S	ite?				
Owner/Operator Information													
Registered Aircraft Owner				Street Address 777 MAIN STREET									
FLEET NATIONAL BANK			City								e	Zip Code	
				HARTFORD CT 06115 Street Address									
Operator of Aircraft	1 EMERY PLAZA												
EMERY WORLDWIDE AIRLINES			City VANDALIA							Stat OH	e	Zip Code 45377	
Operator Does Business As:	<u>'</u>	Operator Designator Code: RRXA											
- Type of U.S. Certificate(s) Held:													
Air Carrier Operating Certificate(s)	Flag Carrier/Don	nestic											
Operating Certificate:				Operator (	Certific	cate:							
Regulation Flight Conducted Unde	r: Part 121: Air Ca	arrier		•									
Type of Flight Operation Conducted			estic; Carg	0									
		FACT	JAL REPO	ORT - AVIAT	ION							Page 2	

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: CHI00LA047

Occurrence Date: 12/17/1999

AVIATI	ON		Occurrence Type: Accident										
First Pilot Information													
Name					City					State	Dat	te of Birth	Age
On File					On File	)			(	On File	Oı	n File	46
Sex: M Seat Occupied	n Pilot				Certif	icate Nu	mber:	On File	•				
Certificate(s): Airline Transport													
Airplane Rating(s): Multi	i-engine Lar	nd; Single-e	ngine Land										
Rotorcraft/Glider/LTA: None													
Instrument Rating(s): Airplane													
Instructor Rating(s):													
Type Rating/Endorsement for	pe Rating/Endorsement for Accident/Incident Aircraft? Yes Current Biennial Flight Review?												
Medical Cert.: Class 1	n.		Date	of Last	Medica	l Exar	n: 11/1999						
	•							_					
- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Night	Night Act		Instrument Simulated		Rotorcra	ıft	Glider	Lighter Than Air
Total Time													
Pilot In Command(PIC)													
Instructor								_		ļ			
Last 90 Days	178	178		178									
Last 30 Days	52	52		52						-			
Last 24 Hours	3	3	1110	3	 		logy Dor	formod?	NI-		Casa	nd Dilata Va	_
Seatbelt Used? Yes	Shou	lder Harness	Used?			OXICO	logy Per	rormea?	No		Seco	nd Pilot? Ye	es .
Flight Plan/Itinerary													
Type of Flight Plan Filed: IF	R												
Departure Point						State	Д	irport Ide	De	Departure Time		Time Zone	
Same as Accident/Incident Location							11	ND		000	0000		
Destination	action						Δ	Airport Identifier					
MINNEAPOLIS								1SP					
Type of Clearance: None													
Type of Airspace: Class	В												
Weather Information													
Source of Briefing: Compa	any												
Method of Briefing:													
	FACTUAL REPORT - AVIATION Page 3									Page 3			

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: CHI00LA047

Occurrence Date: 12/17/1999

Occurrence Type: Accident

	FTYBOR				. , , , , ,	7 1001001							
Weather	Information												
WOF ID	Observation Time	Time Zone	WOF	Elevatio	n	WOF D	istance	From Acci	dent Site	n Accident Site	е		
IND	1356	CST		797 Ft. I	MSL				0 NM	Mag.			
Sky/Lowes	st Cloud Condition: Scat	tered					8500 F	. AGL	Condition of Light: Day				
Lowest Ce	iling: None			0 Ft. A	\GL	Visib	ility:	10	10 SM Altimeter: 30.00				
Temperatu	ıre: 8 °C	Dew Point:		1 °C	Wind	I Direction: 340 Density Altitude:							Ft.
Wind Spee	ed: 8	Gusts:			Weather Condtions at Accident Site: Visual Conditions								
Visibility (F	RVR): 0 Ft.	Visibility	(RVV)	0	SM	Intensit	y of Pre	cipitation:	Unknown				
Restriction	s to Visibility: None												
	None None												
Type of Pro	ecipitation: None												
Accident	Information												
Aircraft Damage: Substantial Aircraft Fire: None Aircraft Explosion None													
	ion: U.S. Registered/U	S Soil											
	mmary Matrix	Fatal	Serious	Minor		None	тота						
First Pi	-				+	1		1					
Second	d Pilot					1		1					
Studen	nt Pilot												
Flight I	nstructor												
Check	Pilot												
Flight E	Engineer					1		1					
Cabin /	Attendants												
Other (	Crew												
Passer	ngers												
- TOTAL A	ABOARD -					3		3					
Other 0	Ground	0	0		0			0					
- GRANE	O TOTAL -	0	0		0	3		3					
_													

National Transportation Safety Board
National Transportation Safety Board
EACTELAL DEDADT

FACTUAL REPORT
AVIATION

NTSB ID: CHI00LA047

Occurrence Date: 12/17/1999

Occurrence Type: Accident

Investigator-In-Charge (IIC)

PAMELA S. SULLIVAN

Additional Persons Participating in This Accident/Incident Investigation:

FRED HIGHT 8303 W. SOUTHERN AVE. INDIANAPOLIS, IN 46241