Engine fire, Boeing 727-100, July 13, 2001

Micro-summary: This Boeing B-727-100 experienced an engine failure on takeoff.

Event Date: 2001-07-13 at 0428 CDT

Investigative Body: National Transportation Safety Board (NTSB), USA

Investigative Body's Web Site: http://www.ntsb.gov/

Cautions:

1. Accident reports can be and sometimes are revised. Be sure to consult the investigative agency for the latest version before basing anything significant on content (e.g., thesis, research, etc).

- 2. Readers are advised that each report is a glimpse of events at specific points in time. While broad themes permeate the causal events leading up to crashes, and we can learn from those, the specific regulatory and technological environments can and do change. Your company's flight operations manual is the final authority as to the safe operation of your aircraft!
- 3. Reports may or may not represent reality. Many many non-scientific factors go into an investigation, including the magnitude of the event, the experience of the investigator, the political climate, relationship with the regulatory authority, technological and recovery capabilities, etc. It is recommended that the reader review all reports analytically. Even a "bad" report can be a very useful launching point for learning.
- 4. Contact us before reproducing or redistributing a report from this anthology. Individual countries have very differing views on copyright! We can advise you on the steps to follow.

Aircraft Accident Reports on DVD, Copyright © 2006 by Flight Simulation Systems, LLC All rights reserved.

www.fss.aero

National Transportation Safety Board	NTSB	D: ATL01IA08	3	Aircraft Registr	Aircraft Registration Number: N189FE Most Critical Injury: None				
FACTUAL REPORT	Occurr	ence Date: 07/1	3/2001	Most Critical Ir					
AVIATION	Occurr	ence Type: Incid	lent	Investigated B	Investigated By: NTSB				
Location/Time									
Nearest City/Place	State	Zip Code	Local Time	Time Zone					
MEMPHIS	TN	38118	0428	CDT					
Airport Proximity: On Airport	n Landing Facility	: 0	Direction Fro	Direction From Airport: 0					
Aircraft Information Summary									
Aircraft Manufacturer	Model/Serie	es .			Type of Aircraft				
Boeing	B-727-100)		Airplane					
Sightseeing Flight: No		Air Medical T	Air Medical Transport Flight: No						

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On July 13, 2001, at 0428 central daylight time, a Boeing B-727-100, N189FE, registered to Federal Express Corporation, experienced a number 3, engine failure and fire during takeoff at the Memphis International Airport in Memphis, Tennessee. The airplane was operated by the Federal Express Corporation under the provisions of Title 14 CFR Part 121, and instrument flight rules. Visual meteorological conditions prevailed and a company IFR Flight plan was filed for the flight to Indianapolis, Indiana. The airline transport pilot, co-pilot and flight engineer were not injured, and the airplane sustained minor damage to the # 3 engine. The flight was originating from Memphis, Tennessee, at the time of the incident.

According to Federal Express the flight had a normal start and taxi to runway 36R. The crew accomplished a normal takeoff using standard power. At 100 feet above ground level (AGL) the #3 engine fire warning light with normal engine indications illuminated. The captain made the takeoff and gave control of the aircraft to the first officer after cleaning up the airplane. The first officer flew visual pattern to runway 36C while the captain and second officer accomplished the engine fire/severe damage checklist. During the procedure the #3 oil low pressure light came on and the #3 generator tripped off. Also, the #3 exhaust gas temperature (EGT) started to rise above the red line and fluctuate. The #3 engine was shut down in accordance with the engine fire/severe damage checklist. The fire warning light did not go out until the second fire bottle was used. An emergency was declared with the tower. The captain took control of the airplane at 1000 feet AGL and made the landing on runway 36C. They made a normal landing and taxied clear of the runway. Emergency crews inspected the airplane and observed no indication of fire. They subsequently did a normal taxi back to the gate and there was a normal shutdown.

Examination of the engine found the starter impeller missing from the starter, however it was found in the engine cowling. The bottom of the lower left side of the engine was burned with holes in the combustion chamber fan duct, but there were no penetrations. The N1 rotor was free to rotate and the fan rotated concurrently with the low pressure turbine. There was no apparent damage to the first stage fan blades and fourth stage turbine blades. The combustion chamber fan duct had two holes and axial split as follows: There was a 4 1/2- inch long axial by 4-inch wide circumferential hole at the 8 o'clock, 18 1/2-inches from the front flange. There was a 6-inch long axial split at the 7 o'clock, 8 1/2-inches from the front flange. There was a 3-inch hole with the edge pedaled outward at the 6 o'clock, 20-inches from the forward flange. The acoustic material was visible in the holes and was intact.

The starter turbine was missing from the starter assembly, but the turbine was recovered from the cowling. The turbine impeller was intact, except for one turbine impeller vane that was broken across the airfoil 1/4-inch above the hub. The fractured airfoil had an approximately 1/8-inch long section of the forward edge that was flat and the remainder of the fracture surface was at a 45 degree angle. All of the tips on the full length airfoils had rub marks with material displaced away from the direction of rotation. The starter shaft was separated 2 1/4-inchs from the impeller.

NTSB ID: ATL01IA083

Occurrence Date: 07/13/2001

Occurrence Type: Incident

The bearing was broken and rubbed flush to the shaft. The ignition exciter box brackets were burned and the box was hanging by the cable. The ignition exciter box was burned open. The engine was not disassembled.

NTSB ID: ATL01IA083

Occurrence Date: 07/13/2001

AVIATION	rence Type: Incident											
Landing Facility/Approach Info	rmation											
Airport Name			Airport ID:	Airport Eleva	tion	Runway Used		Runway Length		h	Runway Widt	
Memphis International Arpt	MEM	332 Ft		36F	6R 9000)0		150			
Runway Surface Type: Asphalt												
Runway Surface Condition: Dry												
Type Instrument Approach: ILS-com	nplete; Visual											
VFR Approach/Landing: Precaution	ary Landing											
Aircraft Information												
Aircraft Manufacturer Boeing			Model	/Series 7-100					Serial 1908	Numbe 2	er	
Airworthiness Certificate(s): Transpo	ort		'									
Landing Gear Type: Retractable - 1	 Fricycle											
Homebuilt Aircraft? No N	lumber of Seats:	 5	Certified Max Gross Wt.				161000 LBS Number			er of Engines: 3		: 3
Engine Type: E				Engine Manufacturer: Model/Series: P&W Canada JT8D-7B						Rated Powe 14000 LBS		
- Aircraft Inspection Information												
Type of Last Inspection			Date of Last Inspection Time Sin			nce Last Insp	Airframe Total Time					
Continuous Airworthiness			07/2001					ours		65531 Hours		
- Emergency Locator Transmitter (EL	T) Information											
ELT Installed? No	ELT Operate	ed? No			ELT	Aided ir	n Locating Ac	cident S	ite? No)		
Owner/Operator Information												
Registered Aircraft Owner			Street A		\DD0		\\/ _					
Federal Express Corporation			2005 CORPORATE AVE. City							Stat	e	Zip Code
			MEMPHIS Street Address									38132
Operator of Aircraft			Same as Reg'd Aircraft Owner									
Same as Reg'd Aircraft Owner			City						Stat	e	Zip Code	
Operator Does Business As:			•			Op	erator Desig	nator Co	de: FD	EA		
- Type of U.S. Certificate(s) Held:												
Air Carrier Operating Certificate(s): C	argo; Flag Carr	ier/Don	nestic; Sup	plemental								
Operating Certificate: Large Aircraf	t Operator			Operator 0	Certific	ate:						
Regulation Flight Conducted Under: Part 121: Air Carrier												
Type of Flight Operation Conducted:	Scheduled; Dor	nestic;	Cargo									
		EACTI	IVI DEDU	ΡΤ - ΔΝΙΔΤ	ION							Page 2

NTSB ID: ATL01IA083

Occurrence Date: 07/13/2001

TACIDAL N	Occurrent	-									
AVIATI ETY BO	WN		Occurrent	Occurrence Type: Incident							
First Pilot Information											
Name	City				ite	Date of Birth	Age				
On File	On File			File	On File	44					
Sex: M Seat Occupied	n Pilot	lot Certificate Number: On File									
Certificate(s): Airline Transport											
Airplane Rating(s): Multi-engine Land											
Rotorcraft/Glider/LTA:											
Instrument Rating(s): Airpl	lane										
Instructor Rating(s): None											
Type Rating/Endorsement for	or Accident/In	cident Aircra	ft? Yes			Current E	iennial Flight	t Reviev	w? 05/2	2001	
Medical Cert.: Class 1	Medica	al Cert. Status	: Unknown	1			Date of	Last Mo	edical E	xam:	
- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Night	Actual	Instrument Simulate		Rotorcraft	Glider	Lighter Than Air
Total Time	4468	3408		4468							
Pilot In Command(PIC)											
Instructor											
Last 90 Days	97	97		97							
Last 30 Days	17	17		17	-						
Last 24 Hours	1	1		1	<u> </u>						
Seatbelt Used? Yes	Shou	lder Harness	Used? Yes		To	oxicology Pe	rformed? No)	S	econd Pilot? Ye	S
Flight Plan/Itinerary											
Type of Flight Plan Filed: IF	R										
Departure Point					s	State Airport		port Identifier		rture Time	Time Zone
Same as Accident/Incide	ent Location						MEM		0428		CDT
Destination					S	tate	Airport Identi	ifier		<u>'</u>	
Indianapolis	IN		IND								
Type of Clearance: IFR											
Type of Airspace: Class B											
Weather Information											
Source of Briefing: Company											
Method of Briefing: Teletype											
FACTUAL REPORT - AVIATION Page 3											

NTSB ID: ATL01IA083

Occurrence Date: 07/13/2001

Occurrence Type: Incident

	PETYBOR		Occurrent	,е туре.	moluem									
Weather	Information													
WOF ID	Observation Time	Time Zone	WOF Elevati	on	WOF Distance From Accident Site					Direction From Accident Site				
MKL	0453	CDT	434 Ft.	MSL	120 NM					180 Deg. Mag.				
Sky/Lowes	st Cloud Condition: Clear	r		Ft. AGL					Condition of Light: Night					
Lowest Ce	iling: Overcast		3600 Ft.	AGL	Visibil	lity:	10	SM	Altir	meter:	29.99	"Hg		
Temperatu	ıre: 23 °C I	Dew Point:	Wind I	Direction:	20			Der	nsity Altitude:	1279	Ft.			
Wind Spee	ed: 6	Gusts:		Weather Condtions at Accident Site: Visual Conditions										
Visibility (R	RVR): Ft.	Visibility (R\	/V)	SM	Intensity	of Precipita	ation:							
Restriction	s to Visibility: None													
Type of Precipitation: None														
Accident	Information													
Aircraft Dar	mage: Minor	e: None	ne Aircraft Exp					None						
Classificati	on: U.S. Registered/U	.S. Soil												
- Injury Su	mmary Matrix	Fatal Ser	rious Mino	or	None	TOTAL								
First Pi	lot				1	1								
Second	d Pilot				1	1								
Studen	it Pilot													
Flight I	nstructor						1							
Check	Pilot						1							
Flight E	Engineer				1	1								
Cabin A	Attendants													
Other C	Crew													
Passen	ngers													
- TOTAL A	ABOARD -				3	3								
Other G	Ground						1							
- GRAND	O TOTAL -				3	3								
				<u>'</u>										

National Transportation Safety Board

FACTUAL REPORT AVIATION

NTSB ID: ATL01IA083

Occurrence Date: 07/13/2001

Occurrence Type: Incident

Administrative Information

Investigator-In-Charge (IIC)

BUTCH WILSON

Additional Persons Participating in This Accident/Incident Investigation:

Wayne Williams Aviation Safety Inspector FAA FSDO-25 3385 Airways Boulevard, Ste 115 Memphis, TN 38116

Gordon J Hookey Transportation Safety Specialist NTSB 490 L'Enfant Plaza East, SW Washington, DC 20594

John M Duke Federal Express Memphis, TN 38116