
In-flight electrical smoke, Boeing 737-229, G-CEAI

Micro-summary: This Boeing 737-229 diverted after detecting electrical smoke.

Event Date: 2002-11-26 at 1833 UTC

Investigative Body: Aircraft Accident Investigation Board (AAIB), United Kingdom

Investigative Body's Web Site: [http://www\(aaib.dft.gov.uk/](http://www(aaib.dft.gov.uk/)

Note: Reprinted by kind permission of the AAIB.

Cautions:

1. Accident reports can be and sometimes are revised. Be sure to consult the investigative agency for the latest version before basing anything significant on content (e.g., thesis, research, etc).
 2. Readers are advised that each report is a glimpse of events at specific points in time. While broad themes permeate the causal events leading up to crashes, and we can learn from those, the specific regulatory and technological environments can and do change. **Your company's flight operations manual is the final authority as to the safe operation of your aircraft!**
 3. Reports may or may not represent reality. Many many non-scientific factors go into an investigation, including the magnitude of the event, the experience of the investigator, the political climate, relationship with the regulatory authority, technological and recovery capabilities, etc. It is recommended that the reader review all reports analytically. Even a "bad" report can be a very useful launching point for learning.
 4. Contact us before reproducing or redistributing a report from this anthology. Individual countries have very differing views on copyright! We can advise you on the steps to follow.
-

Aircraft Accident Reports on DVD, Copyright © 2006 by Flight Simulation Systems, LLC
All rights reserved.

www.fss.aero

Boeing 737-229, G-CEAI

AAIB Bulletin No: 6/2003

Ref: EW/G2002/11/17

Category: 1.1

INCIDENT

| | | |
|--|--|-------------------|
| Aircraft Type and Registration: | Boeing 737-229, G-CEAI | |
| No & Type of Engines: | 2 Pratt & Whitney JT8D-15 turbofan engines | |
| Year of Manufacture: | 1975 | |
| Date & Time (UTC): | 26 November 2002 at 1833 hrs | |
| Location: | Bournemouth International Airport | |
| Type of Flight: | Positioning flight | |
| Persons on Board: | Crew - 2 | Passengers - None |
| Injuries: | Crew - None | Passengers - N/A |
| Nature of Damage: | Minor | |
| Commander's Licence: | Airline Transport Pilot's Licence | |
| Commander's Age: | 55 years | |
| Commander's Flying Experience: | 10,287 hours (of which 277 were on type) | |
| | Last 90 days - 147 hours | |
| | Last 28 days - 36 hours | |
| Information Source: | Aircraft Accident Report Form submitted by the pilot | |

History of the flight

The aircraft was departing from Bournemouth on a positioning flight to London Gatwick Airport. On the initial taxi there were failures of the first officer's IVSI (Instantaneous Vertical Speed Indicator), the weather radar transmitter/receiver and the wheelbrakes ANTISKID INOP failure captions had illuminated. The aircraft returned to its departure stand where the engineers replaced the IVSI and weather radar. They also traced the anti-skid problem to a loose connection at a terminal block and rectified this problem. G-CEAI then taxied out again and took off.

Shortly after being cleared by London Area Control Centre (LACC) from FL70 to FL80 the first officer selected ALT SEL on the autopilot mode control panel. The ALT ACQUIRE caption illuminated rather than the expected ALT SEL caption so the crew reselected, with the same outcome. The antiskid failure captions then illuminated brightly, although the panel was selected for dim illumination.

As the pilots discussed returning to Bournemouth because of these anomalies, all the remaining captions illuminated accompanied by a distinct smell of electrical burning. The crew immediately declared a MAYDAY to LACC, announced their intention of returning immediately to Bournemouth, donned their emergency oxygen masks and started their descent. LACC requested a transponder code of 7700 and handed control of the flight to Bournemouth Approach. The crew were unable to locate

the source of the fumes so they concentrated on the normal checklists and landing safely as soon as possible.

After the landing, the crew shut down the aircraft with the fire service in attendance. No fumes were detected so the aircraft was evacuated via a fire ladder at the front left passenger door. The pilots were both given oxygen because they were suffering from light-headedness and tingling in the fingers.

Technical examination

After the crew left the aircraft the ground engineers disconnected the battery and the aircraft was towed back to the hangar.

The initial visual examination did not reveal any evidence of burning so the investigation continued, initially with the battery, then the APU and finally with both engines running, with their respective generators connected. No smoke or fumes were detected so the engines were shut down and the other aircraft systems were then functioned in turn.

When the Altitude Alert Unit (AAU) was checked, the warning lights flickered and the circuit breaker for Zone 6 popped. Examination of the AAU control unit did not show any fault but when the co-pilot's annunciator was examined, there was evidence of burning in the connector. With the annunciator disconnected, the system functioned without disturbing the circuit breaker.

The burning appeared to have been caused by water ingress into the flight deck. A check with a hose pipe playing water over the windscreen area (with power off!) showed a slight leak from the co-pilot's windscreens and a larger leak from the windscreen wiper sealing boot. After the windscreen was resealed and the boot replaced subsequent further leak checks were satisfactory.

The aircraft maintenance company considers that the failure of the IVSI was probably also an indication of water ingress as it is the only electrical unit in that area with cooling holes. The company also decided to check for water ingress behind the instrument panel at the next hangar visit for the remainder of the Boeing 737 fleet and the inspection will be repeated at each C check.