
Noxious fumes, Boeing 757-236, G-CPET, March 10, 2006

Micro-summary: Following engine start, the flight crew felt ill.

Event Date: 2006-03-10 at 0810 UTC

Investigative Body: Aircraft Accident Investigation Board (AAIB), United Kingdom

Investigative Body's Web Site: <http://www.aaib.dft.gov.uk/>

Note: Reprinted by kind permission of the AAIB.

Cautions:

1. Accident reports can be and sometimes are revised. Be sure to consult the investigative agency for the latest version before basing anything significant on content (e.g., thesis, research, etc).
 2. Readers are advised that each report is a glimpse of events at specific points in time. While broad themes permeate the causal events leading up to crashes, and we can learn from those, the specific regulatory and technological environments can and do change. ***Your company's flight operations manual is the final authority as to the safe operation of your aircraft!***
 3. Reports may or may not represent reality. Many many non-scientific factors go into an investigation, including the magnitude of the event, the experience of the investigator, the political climate, relationship with the regulatory authority, technological and recovery capabilities, etc. It is recommended that the reader review all reports analytically. Even a "bad" report can be a very useful launching point for learning.
 4. Contact us before reproducing or redistributing a report from this anthology. Individual countries have very differing views on copyright! We can advise you on the steps to follow.
-

INCIDENT

Aircraft Type and Registration:	Boeing 757-236, G-CPET	
No & Type of Engines:	2 Rolls-Royce RB211-535E4-37 turbofan engines	
Year of Manufacture:	1998	
Date & Time (UTC):	10 March 2006 at 0810 hrs	
Location:	London Heathrow Airport	
Type of Flight:	Public Transport (Passenger)	
Persons on Board:	Crew - 7	Passengers - 149
Injuries:	Crew - None	Passengers - None
Nature of Damage:	None	
Commander's Licence:	Airline Transport Pilot's Licence	
Commander's Age:	35 years	
Commander's Flying Experience:	7,165 hours (of which 5,505 were on type) Last 90 days - 195 hours Last 28 days - 80 hours	
Information Source:	Aircraft Accident Report Form submitted by the pilot	

Synopsis

After engine start, the crew were aware of an unusual odour in the cockpit and both started to feel unwell. Investigation suggested that a suspect oil leakage in the left engine may have been responsible for the smell.

Both engines were shut down as the crew no longer felt fit to taxi the aircraft and it was towed back to the stand. During the tow, the co-pilot donned his oxygen mask.

History of the flight

After starting both engines, the co-pilot reported that he could smell fumes and discussed the matter with the commander. After about two minutes of taxiing, the co-pilot started to feel light-headed, euphoric and unwell, the commander also felt light-headed and the aircraft was halted on the taxiway to see if the situation improved. Both flight crew members continued to feel abnormal - the co-pilot considered himself partially incapacitated – but the cabin staff appeared unaffected.

The aircraft was withdrawn from service and the flight crew were stood-down after they had briefed the maintenance staff about the problem and had pointed out that there had been a previous entry in the technical log on 4 March 2006 concerning an 'occasional brief smell of oil on the flight deck. No smell in cabin'. During a check by engineering, no traces of oil were found and the aircraft had been returned to service.

Examination of the aircraft this time (10 March 2006) revealed one defect which may have contributed to

the smell: staining on the oil feed tubes feeding the front bearing of the left engine appeared to indicate a leakage of oil into the gas path. However, it could not

be established categorically that this was the source of the fumes and, having investigated the suspect leak, the aircraft was returned to service.