
Nose gear collapse on landing, McDonnell Douglas DC-9-82, September 1, 1997

Micro-summary: This September 1, 1997 experienced a collapse of the nose landing gear on landing.


Event Date: 1997-09-01 at 2110 PDT


Investigative Body: National Transportation Safety Board (NTSB), USA

Investigative Body's Web Site: <http://www.nts.gov/>

Cautions:

1. Accident reports can be and sometimes are revised. Be sure to consult the investigative agency for the latest version before basing anything significant on content (e.g., thesis, research, etc).
 2. Readers are advised that each report is a glimpse of events at specific points in time. While broad themes permeate the causal events leading up to crashes, and we can learn from those, the specific regulatory and technological environments can and do change. ***Your company's flight operations manual is the final authority as to the safe operation of your aircraft!***
 3. Reports may or may not represent reality. Many many non-scientific factors go into an investigation, including the magnitude of the event, the experience of the investigator, the political climate, relationship with the regulatory authority, technological and recovery capabilities, etc. It is recommended that the reader review all reports analytically. Even a "bad" report can be a very useful launching point for learning.
 4. Contact us before reproducing or redistributing a report from this anthology. Individual countries have very differing views on copyright! We can advise you on the steps to follow.
-

		NTSB ID: SEA97FA202		Aircraft Registration Number: N951AS	
		Occurrence Date: 09/01/1997		Most Critical Injury: Minor	
		Occurrence Type: Accident		Investigated By: NTSB	
Location/Time					
Nearest City/Place SEATTLE		State WA	Zip Code 98188	Local Time 2110	Time Zone PDT
Airport Proximity: On Airport		Distance From Landing Facility:		Direction From Airport:	
Aircraft Information Summary					
Aircraft Manufacturer McDonnell Douglas		Model/Series DC-9-82 (MD-82)		Type of Aircraft Airplane	
Sightseeing Flight: No			Air Medical Transport Flight: No		
Narrative					
<p>Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:</p> <p>HISTORY OF FLIGHT</p> <p>On September 1, 1997, at 2110 Pacific daylight time, N951AS, a McDonnell-Douglas DC-9-82 (MD-82), operating as Alaska Airlines flight 255 from Los Angeles, California, to Seattle, Washington, sustained substantial damage when its nose landing gear collapsed during landing roll-out on runway 16L at Seattle-Tacoma International Airport. The two flight crewmembers and three flight attendants were uninjured. Seventeen of the 111 passengers incurred minor injuries during the emergency evacuation commanded by the captain after the airplane slid to a stop. There was no fire.</p> <p>According to the flight crewmembers, the airplane had departed Los Angeles, California with no indication of vibration or other abnormality. The flight was uneventful until the landing gear was extended and the nose landing gear warning light indicated an unsafe landing gear indication. At that time, the crew initiated a go-around (retracting the landing gear), climbed to a safe altitude in safe airspace, and then completed appropriate checklists in an attempt to obtain a safe gear-down indication with the landing gear extended. After completing appropriate checklists, the mechanical nose landing gear position indicator indicated that the nose landing gear was extended in a down and locked position, while the light continued to indicate an unsafe condition. The crew elected to land, and requested emergency equipment standing by.</p> <p>The captain stated that he landed the airplane smoothly; at about 60 knots indicated airspeed, the nose settled onto the runway and the airplane slid to a stop. The airplane slid about 1300 feet and drifted slightly to the right of centerline. He commanded an evacuation. All slides were deployed manually and the passengers evacuated quickly.</p> <p>During the course of recovering the airplane from the runway, it was determined that the nose landing gear upper lock link, part number 3914464-503, had failed, separating into two pieces. This item, which is subject to recurring non-destructive testing every 5000 cycles according to AD 97-02-10, had undergone an eddy current inspection 1075 cycles previous to the accident. This part was one of a series manufactured from plate stock, rather than being forged. Due to this changed process, according to the aircraft manufacturer, the lack of draft angle allowances on the machined parts reduced the load-carrying cross sectional area of the machined links to less than that of the forged links, resulting in a decrease in the overall strength. Metallurgical analysis revealed that approximately 10,000 major fatigue progression cycles had occurred within about .6 inches of the crack progression. Based upon the manufacturer's determination that there are two major stress cycles per gear retraction/extension cycle, the expected crack length 1075 cycles prior to the accident would have been greater than .25 inches.</p> <p>The Safety Board determined that there have been seven cracked or fractured upper lock links reported; all have RM serial numbers indicating that they came from Ready Machine, a now-defunct supplier to the airplane manufacturer.</p>					
FACTUAL REPORT - AVIATION					

 <p>National Transportation Safety Board FACTUAL REPORT AVIATION</p>	NTSB ID: SEA97FA202	
	Occurrence Date: 09/01/1997	
	Occurrence Type: Accident	

Narrative (Continued)

INJURIES TO PERSONS

Nineteen individuals sustained minor injuries during the evacuation, including three with neck or back pain or spasms, some knee injuries, and one with a sprained ankle.

FLIGHT RECORDERS

The flight data recorder readout for the approach, landing, and landing rollout is attached.

WRECKAGE AND IMPACT INFORMATION

The airplane was inspected on-scene. The cockpit switches and controls were found to be secured. Their positions were not recorded. The cockpit crew side windows were open and the cockpit door was locked. During interviews, the flight crew noted that after calling for evacuation, they had evacuated out the cockpit windows.

Damage included nose gear doors, skin scraping, and a wrinkled forward pressure bulkhead. During the course of on-scene investigation, it was noted that the jump seat at the mid-cabin flight attendant position was not retracted. The flight attendant at that duty station at the time of the accident noted that she did not notice that anomaly until after the evacuation was completed, and noted that it did not hamper the evacuation.


TESTS AND RESEARCH


The nose landing gear upper lock link, P/N 3914464-503, s/n RM 486, was analyzed by the material laboratory division of the NTSB. The metallurgist's factual report is attached.


The inspection procedure and process provided by the airframe manufacturer does not specify removal of the upper lock link from the aircraft prior to recurring non-destructive tests (NDT). During the course of investigation, NTSB investigators and FAA inspectors observed that access to the upper lock link for NDT is limited when the part remains installed in the airplane.

ADDITIONAL INFORMATION

The aircraft was moved from the scene to the Alaska Airlines maintenance facility at SEATAC airport on the night of the accident. The Safety Board did not take possession of the wreckage.

 National Transportation Safety Board FACTUAL REPORT AVIATION		NTSB ID: SEA97FA202				
		Occurrence Date: 09/01/1997				
		Occurrence Type: Accident				
Landing Facility/Approach Information						
Airport Name SEATTLE-TACOMA INTL		Airport ID: KSEA	Airport Elevation 420 Ft. MSL	Runway Used 16L	Runway Length 11900	Runway Width 150
Runway Surface Type: Asphalt						
Runway Surface Condition: Dry						
Type Instrument Approach: NONE						
VFR Approach/Landing: Full Stop						
Aircraft Information						
Aircraft Manufacturer McDonnell Douglas		Model/Series DC-9-82 (MD-82)		Serial Number 49111		
Airworthiness Certificate(s): Transport						
Landing Gear Type: Retractable - Tricycle						
Homebuilt Aircraft? No		Number of Seats: 138		Certified Max Gross Wt. 149500 LBS	Number of Engines: 2	
Engine Type: Turbo Fan		Engine Manufacturer: P&W		Model/Series: JT8D-217	Rated Power: 20800 LBS	
- Aircraft Inspection Information						
Type of Last Inspection AAIP		Date of Last Inspection 08/1997		Time Since Last Inspection Hours	Airframe Total Time 45378 Hours	
- Emergency Locator Transmitter (ELT) Information						
ELT Installed?		ELT Operated?		ELT Aided in Locating Accident Site?		
Owner/Operator Information						
Registered Aircraft Owner INTEGRATED AIRCRAFT SERVICES		Street Address 10 UNION SQUARE EAST				
		City NEW YORK		State NY	Zip Code 10003	
Operator of Aircraft ALASKA AIRLINES		Street Address BOX 68900				
		City SEATTLE		State WA	Zip Code 98168	
Operator Does Business As:				Operator Designator Code: ASAA		
- Type of U.S. Certificate(s) Held:						
Air Carrier Operating Certificate(s): Flag Carrier/Domestic						
Operating Certificate:			Operator Certificate:			
Regulation Flight Conducted Under: Part 121: Air Carrier						
Type of Flight Operation Conducted: Scheduled; Domestic; Passenger Only						
FACTUAL REPORT - AVIATION						

 National Transportation Safety Board FACTUAL REPORT AVIATION			NTSB ID: SEA97FA202																																																																																			
			Occurrence Date: 09/01/1997																																																																																			
			Occurrence Type: Accident																																																																																			
First Pilot Information																																																																																						
Name On File			City On File		State On File	Date of Birth On File	Age 47																																																																															
Sex: M	Seat Occupied: Left		Principal Profession: Civilian Pilot			Certificate Number: On File																																																																																
Certificate(s): Airline Transport																																																																																						
Airplane Rating(s): Multi-engine Land; Single-engine Land																																																																																						
Rotorcraft/Glider/LTA: None																																																																																						
Instrument Rating(s): Airplane																																																																																						
Instructor Rating(s): Instrument Airplane																																																																																						
Type Rating/Endorsement for Accident/Incident Aircraft? Yes					Current Biennial Flight Review?																																																																																	
Medical Cert.: Class 1		Medical Cert. Status: Valid Medical--w/ waivers/lim.			Date of Last Medical Exam: 03/1997																																																																																	
<table border="1"> <thead> <tr> <th rowspan="2">- Flight Time Matrix</th> <th rowspan="2">All A/C</th> <th rowspan="2">This Make and Model</th> <th rowspan="2">Airplane Single Engine</th> <th rowspan="2">Airplane Multi-Engine</th> <th rowspan="2">Night</th> <th colspan="2">Instrument</th> <th rowspan="2">Rotorcraft</th> <th rowspan="2">Glider</th> <th rowspan="2">Lighter Than Air</th> </tr> <tr> <th>Actual</th> <th>Simulated</th> </tr> </thead> <tbody> <tr> <td>Total Time</td> <td>27388</td> <td>1491</td> <td>800</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Pilot In Command(PIC)</td> <td>18068</td> <td>1306</td> <td>100</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Instructor</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Last 90 Days</td> <td>222</td> <td>222</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Last 30 Days</td> <td>69</td> <td>69</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Last 24 Hours</td> <td>5</td> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>								- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Multi-Engine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air	Actual	Simulated	Total Time	27388	1491	800								Pilot In Command(PIC)	18068	1306	100								Instructor											Last 90 Days	222	222									Last 30 Days	69	69									Last 24 Hours	5	5								
- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Multi-Engine	Night	Instrument								Rotorcraft	Glider				Lighter Than Air																																																																			
						Actual	Simulated																																																																															
Total Time	27388	1491	800																																																																																			
Pilot In Command(PIC)	18068	1306	100																																																																																			
Instructor																																																																																						
Last 90 Days	222	222																																																																																				
Last 30 Days	69	69																																																																																				
Last 24 Hours	5	5																																																																																				
Seatbelt Used? Yes		Shoulder Harness Used? Yes			Toxicology Performed? No		Second Pilot? Yes																																																																															
Flight Plan/Itinerary																																																																																						
Type of Flight Plan Filed: IFR																																																																																						
Departure Point		State		Airport Identifier		Departure Time		Time Zone																																																																														
LOS ANGELES		CA		KLAX		1821		PDT																																																																														
Destination		State		Airport Identifier																																																																																		
Same as Accident/Incident Location				KSEA																																																																																		
Type of Clearance: IFR																																																																																						
Type of Airspace: Class B																																																																																						
Weather Information																																																																																						
Source of Briefing: Company																																																																																						
Method of Briefing:																																																																																						

 National Transportation Safety Board FACTUAL REPORT AVIATION		NTSB ID: SEA97FA202			
		Occurrence Date: 09/01/1997			
		Occurrence Type: Accident			

Weather Information					
WOF ID	Observation Time	Time Zone	WOF Elevation	WOF Distance From Accident Site	Direction From Accident Site
	0000		0 Ft. MSL	0 NM	0 Deg. Mag.
Sky/Lowest Cloud Condition: Clear			0 Ft. AGL	Condition of Light: Night/Dark	
Lowest Ceiling: Broken		3800 Ft. AGL		Visibility: 10 SM	Altimeter: 30.00 "Hg
Temperature: 19 °C	Dew Point: 13 °C	Wind Direction: 220			Density Altitude: Ft.
Wind Speed: 6	Gusts:	Weather Conditions at Accident Site: Visual Conditions			
Visibility (RVR): 0 Ft.	Visibility (RVV) 0 SM	Intensity of Precipitation: Unknown			
Restrictions to Visibility: None					
Type of Precipitation: None					

Accident Information					
Aircraft Damage: Substantial		Aircraft Fire: None		Aircraft Explosion: None	
Classification: U.S. Registered/U.S. Soil					

- Injury Summary Matrix	Fatal	Serious	Minor	None	TOTAL
First Pilot				1	1
Second Pilot				1	1
Student Pilot					
Flight Instructor					
Check Pilot					
Flight Engineer					
Cabin Attendants				3	3
Other Crew					
Passengers			19	92	111
- TOTAL ABOARD -			19	97	116
Other Ground	0	0	0		0
- GRAND TOTAL -	0	0	19	97	116

National Transportation Safety Board

FACTUAL REPORT**AVIATION**

NTSB ID: SEA97FA202

Occurrence Date: 09/01/1997

Occurrence Type: Accident

Administrative Information

Investigator-In-Charge (IIC)

MICHAEL L. STOCKHILL

Additional Persons Participating in This Accident/Incident Investigation:

WILLIAM WHITAKER
SEATTLE FSDO
RENTON, WA 98055

TERRY CLARK
ALASKA AIRLINES
SEATTLE, WA 98168

JOHN BENTLEY
ALPA
RENTON, WA 98055

RONDA RUDERMAN
AFA
SEATTLE, WA 98168