Turbulence injury, Boeing 737-300, December 13, 1998

Micro-summary: This Boeing 737-300 experienced turbulence during descent, seriously injuring a flight attendant.

Event Date: 1998-12-13 at 1840 PST

Investigative Body: National Transportation Safety Board (NTSB), USA

Investigative Body's Web Site: http://www.ntsb.gov/

Cautions:

- 1. Accident reports can be and sometimes are revised. Be sure to consult the investigative agency for the latest version before basing anything significant on content (e.g., thesis, research, etc).
- 2. Readers are advised that each report is a glimpse of events at specific points in time. While broad themes permeate the causal events leading up to crashes, and we can learn from those, the specific regulatory and technological environments can and do change. Your company's flight operations manual is the final authority as to the safe operation of your aircraft!
- 3. Reports may or may not represent reality. Many many non-scientific factors go into an investigation, including the magnitude of the event, the experience of the investigator, the political climate, relationship with the regulatory authority, technological and recovery capabilities, etc. It is recommended that the reader review all reports analytically. Even a "bad" report can be a very useful launching point for learning.
- 4. Contact us before reproducing or redistributing a report from this anthology. Individual countries have very differing views on copyright! We can advise you on the steps to follow.

Aircraft Accident Reports on DVD, Copyright © 2006 by Flight Simulation Systems, LLC All rights reserved.

www.fss.aero

National Transportation Safety Board NTSB ID: LAX99LA050 Aircraft Registration Number: N328AW FACTUAL REPORT Occurrence Date: 12/13/1998 Most Critical Injury: Serious ÁVIATION Occurrence Type: Accident Investigated By: NTSB Location/Time Nearest City/Place State Zip Code Local Time Time Zone 1840 PST CA 95814 SACRAMENTO Distance From Landing Facility: Direction From Airport: Airport Proximity: Off Airport/Airstrip Aircraft Information Summary Aircraft Manufacturer Model/Series Type of Aircraft Boeing 737-300 Airplane

Narrative

Sightseeing Flight: No

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On December 13, 1998, at 1840 hours Pacific standard time, a Boeing 737-300, N328AW, encountered turbulence during descent for landing at Sacramento, California. One flight attendant was seriously injured. The other 4 crewmembers and 70 passengers were not injured, and the aircraft was not damaged. Visual meteorological conditions prevailed for the regularly scheduled domestic passenger flight. The flight was operated on an instrument flight rules flight plan under 14 CFR Part 121 by America West Airlines as flight 378. The flight departed Santa Ana, California at 1750.

Air Medical Transport Flight: No

According to statements provided by America West Airlines, prior to descent from cruise, the cockpit crew advised the second flight attendant, who was later injured, and the third flight attendant by intercom that turbulence was anticipated during descent for landing and for them to secure the cabin and be seated. The second attendant notified the first attendant who directed her attention toward securing first class. The second flight attendant proceeded through the cabin from front to rear, with a trash bag, picking up service items and ensuring that passenger's seat belts were fastened. As she reached the rear of the cabin, turbulence was encountered and both she and the third flight attendant, who was working in the rear galley, took seats and fastened their seatbelts. After 1 or 2 minutes of moderate turbulence, the turbulence ceased and the second and third flight attendants got up to finish their work in the aft galley. Additional turbulence was then encountered which caused the second flight attendant to fall to the floor of the galley. The third flight attendant also fell but landed on the foot of the second attendant, which broke the second attendant's ankle.

The Safety Board investigator reviewed the aircraft's flight data recorder output. As the aircraft descended from flight level 310 (approximately 31,000 feet) the vertical acceleration values recorded remained between 0.85 and 1.06 g's until descending through flight level 200 (approximately 20,000 feet). Between flight level 200 and 7,500 feet mean sea level (msl) in the descent, vertical acceleration values ranged from a low of 0.53 to a high of 2.02 g's. The peak values occurred 5 seconds from one another while the aircraft was descending through 19,832 feet at time 33:41. The vertical acceleration dropped to 0.65 g's and 1 second later increased to 2.02 g's. In the next 4 seconds, values of 1.23, 1.16, 1.45 and 0.53 g's were recorded. Below 7,500 feet the vertical acceleration values returned to the 0.85 to 1.19 range.

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: LAX99LA050

Occurrence Date: 12/13/1998

AVIATION	curren	ence Type: Accident												
Landing Facility/Approach In	forma	tion												
Airport Name				Airport ID: Airport Elevation			Run	way Used	Runway Lengt		h R	unway Width		
					Ft	. MSL	. 0							
Runway Surface Type:			1		<u> </u>				1					
Runway Surface Condition:														
•														
Type Instrument Approach:														
VFR Approach/Landing:														
Aircraft Information														
Aircraft Manufacturer				Model/Series							Serial Number			
Boeing				737-3	800					2337	23377			
Airworthiness Certificate(s): Trans	port													
Landing Gear Type: Retractable	- Tricy	rcle												
Homebuilt Aircraft? No		Certifie	d Max Gross V	139000 LBS Numbe			er of Engines: 2							
					Engine Manufacturer: Model/Series: CFM56-3B2							ated Power: 22000 LBS		
- Aircraft Inspection Information														
Type of Last Inspection			Dat	e of Las	t Inspection	nce Last Insp	ection	Airframe	Total Time					
Continuous Airworthiness				08/1998					1098 Hours			41558 Hours		
- Emergency Locator Transmitter (ELT) lı	nformation												
ELT Installed? No		ELT Operated?				ELT	Γ Aided i	n Locating Ad	ccident S	ite?				
Owner/Operator Information														
Registered Aircraft Owner					Street Address 79 S. MAIN ST.									
FIRST SECURITY BANK					79 3. 1017	State	Zip Code							
				City	SALT LA	KE (CITY				UT	84111		
Operator of Aircraft				Street A		01/1/		ND DL V/D						
Operator of Aircraft	-	4000 E. SKY HARBOR BLVD. City State Zip Code								Zip Code				
AMERICA WEST AIRLINES, INC.					PHOENIX						AZ	85034		
Operator Does Business As:		Operator Designator Code: AWXA								•				
- Type of U.S. Certificate(s) Held:														
Air Carrier Operating Certificate(s)	Flag	Carrier/Domestic	;											
Operating Certificate:					Operator (Certific	cate:							
Regulation Flight Conducted Unde	r: Part	121: Air Carrier			1 -									
Type of Flight Operation Conducted			c: Pas	ssenger	· Onlv									
71		·			<u> </u>									
		FAC	ΓUAL	L REPO	RT - AVIAT	ION						Page 2		

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: LAX99LA050

Occurrence Date: 12/13/1998

	AVIATI	Occurrence Type: Accident											
First Pilot	t Information			•					•				
Name	City					State	Date of Birth	Age					
On File		On File				c	n File	On File	33				
Sex: M	n Pilot	t Certificate Number: On File											
Certificate(s): Airline Transport; Flight Instructor; Flight Engineer													
Airplane Ra	ating(s): Multi	i-engine Lar	nd; Single-e	ngine Land	l; Single-en	gine Se	ea						
Rotorcraft/0	Glider/LTA: None	e											
Instrument Rating(s): Airplane													
Instructor Rating(s): Airplane Single-engine; Instrument Airplane													
Type Rating/Endorsement for Accident/Incident Aircraft? Yes Current Biennial Flight Review?													
Medical Ce	rt.: Class 1	Medica	al Cert. Statu	s: Valid Me	dicalno wa	aivers/l	im.		Date	of Last	Medical I	Exam: 11/1998	
		I											
- Flight Tim	ne Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Nig	ht	Actual	Instrument ual Simulated		Rotorcraft	Glider	Lighter Than Air
Total Time		11000											
Pilot In Cor	mmand(PIC)												
Instructor													
Last 90 Day	ys	135	135		135								
Last 30 Da	·	45	45		45	-							
Last 24 Ho		5	5		5	<u> </u>					<u> </u>		
Seatbelt Us	sed? Yes	Shou	lder Harness	Used? Yes	<u> </u>		Toxico	ology Per	formed?	No		Second Pilot? Yo	es
Flight Pla	n/Itinerary												
	ght Plan Filed: IF	R											
Departure F	Point					T	State	1	Airport Identifier		Depa	arture Time	Time Zone
SANTA A	NA						CA	5	SNA		1750		PST
Destination								<i>F</i>	Airport Identifier				
Same as Accident/Incident Location									SMF				
Type of Cle	earance: IFR							•					
Type of Air	space: Class	A											
Weather	Information												
Source of	Briefing: Compa	any											
Method of	Briefing:												
FACTUAL REPORT - AVIATION Page 3											Page 3		

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: LAX99LA050

Occurrence Date: 12/13/1998

Occurrence Type: Accident

	FTYBOR				. , , ,	10010011							
Weather Information													
WOF ID	Observation Time	Time Zone	WOF	Elevation		WOF Di	NOF Distance From Accident Site Direction F					on From Accident Site	
SMF	0253	PST		0 Ft. M	SL	0 NM					0 Deg. Mag.		
Sky/Lowes	st Cloud Condition: Unk	nown		0 Ft. AGL					Condition of Light: Night/Dark				
Lowest Ce	iling: Overcast	38	3800 Ft. AGL			lity:	10	SM	SM Altimeter:		30.00	"Hg	
Temperatu	ıre: 9 °C		8 °C Wind Direction: 180						Density Altitude: Ft.				
Wind Spee	ed: 8		Weather Condtions at Accident Si					ite: Visual C	ond	itions			
Visibility (F	RVR): 0 Ft.	y (RVV)	0 8	SM	Intensity of Precipitation: Unknown								
Restrictions to Visibility: None													
Type of Precipitation: None													
Accident	Information												
Aircraft Da	mage: None	Airc	Aircraft Fire: None					Aircraft Exp	losio	None			
Classificat	on: U.S. Registered/L	I.S. Soil											
- Injury Su	mmary Matrix	Fatal	Serious	Minor	N	None	TOTAL						
First Pi	ilot					1	1						
Second	d Pilot					1	1	1					
Studer	nt Pilot							1					
Flight I	nstructor							1					
Check	Pilot							1					
Flight E	Engineer												
Cabin /	Attendants		1			2	3	1					
Other (Crew							1					
Passer	ngers					70	70						
- TOTAL /	ABOARD -		1			74	75	1					
Other (Ground	0	0		0		0	1					
- GRANI	O TOTAL -	0	1		0	74	75	1					

National Transportation Safety Board

FACTUAL REPORT AVIATION

Occurrence Date: 12/13/1998

Occurrence Type: Accident

Administrative Information

Investigator-In-Charge (IIC)

RICHARD B. PARKER

Additional Persons Participating in This Accident/Incident Investigation:

RAY C STEINKRAUS FAA FLT STNDS DIST OFFICE SACRAMENTO, CA 95822

DAVID L HUNTZINGER AMERICA WEST AIRLINES, INC. PHOENIX, AZ 85034

JOSEPH BRACKEN AIR LINE PILOTS ASSOC. WASHINGTON, DC 20594