Injury while closing cargo door, Boeing 727, January 13, 1999

Micro-summary: A ground handler was injured while attempting to close the cargo door of a Boeing 727.

Event Date: 1999-01-13 at 1655 EST

Investigative Body: National Transportation Safety Board (NTSB), USA

Investigative Body's Web Site: http://www.ntsb.gov/

Cautions:

- 1. Accident reports can be and sometimes are revised. Be sure to consult the investigative agency for the latest version before basing anything significant on content (e.g., thesis, research, etc).
- 2. Readers are advised that each report is a glimpse of events at specific points in time. While broad themes permeate the causal events leading up to crashes, and we can learn from those, the specific regulatory and technological environments can and do change. Your company's flight operations manual is the final authority as to the safe operation of your aircraft!
- 3. Reports may or may not represent reality. Many many non-scientific factors go into an investigation, including the magnitude of the event, the experience of the investigator, the political climate, relationship with the regulatory authority, technological and recovery capabilities, etc. It is recommended that the reader review all reports analytically. Even a "bad" report can be a very useful launching point for learning.
- 4. Contact us before reproducing or redistributing a report from this anthology. Individual countries have very differing views on copyright! We can advise you on the steps to follow.

Aircraft Accident Reports on DVD, Copyright © 2006 by Flight Simulation Systems, LLC All rights reserved.

www.fss.aero

| NTSB ID: NYC99LA235 | Aircraft Registration Number: N785AT |
|-----------------------------|--------------------------------------|
| Occurrence Date: 01/13/1999 | Most Critical Injury: Serious |
| Occurrence Type: Accident | Investigated By: NTSB |

Location/Time

| Nearest City/Place | State | Zip Code | Local Time | Time Zone | |
|-------------------------------|---------------|---------------------|------------|---------------|------------|
| NEW YORK | NY | 11371 | 1655 | EST | |
| Airport Proximity: On Airport | Distance From | m Landing Facility: | | Direction Fro | m Airport: |

Aircraft Information Summary

| 7 mortan morniamen Garmany | | | | | | | | | |
|----------------------------|--------------|------------------|--|--|--|--|--|--|--|
| Aircraft Manufacturer | Model/Series | Type of Aircraft | | | | | | | |
| Boeing | 727-200 | Airplane | | | | | | | |

Sightseeing Flight: No Air Medical Transport Flight: No

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On January 13, 1999, about 1655 Eastern Standard Time, a ground support handler was seriously injured when a cargo door strut on a Boeing 727-200, N785AT, crushed her hand. At the time, the airplane, which was operating as American Trans Air flight 751/752, was parked at a gate at La Guardia International Airport (LGA), New York, New York. The captain, first officer, second officer, 4 flight attendants, and 153 passengers were uninjured. The flight was preparing to depart, operating under 14 CFR Part 121.

According to a written statement by the handler, her supervisor told her to close one of the cargo doors. The handler wrote:

"The baggage compartment doors are held wide open above and perpendicular to the fuselage of the 727 by an expandable metal bar. The expandable metal bar is connected to the inside and left hand side (looking at the bar from the inside) of the door and it latches into a notch on the right hand side (looking at it from the outside) of the fuselage of the airplane.

I attempted to close the aft baggage compartment door, but when I tried to undo the latch, the bar violently popped out of the notch. The door came crashing down at high velocities, the bar swung into the belly of the aircraft with my hand. With that, the bar penetrating, crushing and tearing the left palm between the pointer finger and thumb, also injuring arm/shoulder/neck."

The accident was not reported by the airline. It was reported to the Safety Board by the injured handler in August 1999, and confirmed in September 1999. According to the airline's director of safety, the handler had worked for Signature Flight Support, which provided the ground support to the airline at La Guardia. The airline was unaware of the accident because Signature had not reported it.

In a letter to the airline dated August 18,1999, the handler's supervisor wrote that the handler had reported to work on the day of the accident after recuperating for a couple of days, from a lower back injury. She was going to be on light duty, and was instructed to only wing walk and assist with radio communications. The supervisor also stated that the handler was signed off to work on the ramp and on the Boeing 727, and that she had "received on-the-job training for this particular task."

In another statement dated January 13, 1999, the supervisor stated that when he asked the handler what happened, she said that the door came down on her while she was closing it. "She was holding the bar that braces the door up with her right hand. It probably came down on her too hard, and she couldn't handle it...."

In an undated statement, a witness wrote that he saw the handler pull out the bar that secured the baggage door when it was it open. "She lost control of the bar, turn[ed] side way[s] to brace from

NTSB ID: NYC99LA235

Occurrence Date: 01/13/1999

Occurrence Type: Accident

Narrative (Continued)

the impact of the aircraft door. The door hit her and she fell to the ground...."

The Boeing 727 maintenance manual excerpt provided by the airline stated that the aft cargo door was a plug-type, outward-upward opening door. The door was equipped with two balance mechanisms to counterbalance the weight of the door to facilitate door opening. The forward balance mechanism had a rotary snubber to prevent the door from opening or closing with excessive force. A support strut was also present, to secure each door in the fully open position.

The maintenance manual also stated that the cargo door would have been closed "by removing the support strut from the fuselage fitting, telescoping the strut and stowing it in the slotted bracket by the door....The cargo door then swings down...."

The ground service manual in use included the following procedure: "Pull cargo door down using Support Strut."

According to the airline's maintenance records, a discrepancy was written up on the cargo door, dated December 25, 1998. It stated: "Aft cargo door heavy to open." The corrective action was: "Found fwd counterbalance hinge loose from mount. Resecured counterbalance hinge as required. Ops check good at this time."

On February 7, 1999, the following discrepancy was written: "Aft cargo door heavy when opening." The following day, the corrective action was: "Adjusted cable tension on fwd balance as required...."

The airline also reported that on the day of the accident, a daily service check was performed on the airplane. Part of the service check required a visual inspection of the cargo bay area, which required the mechanic to open, and then secure, the cargo bay door.

NTSB ID: NYC99LA235

Occurrence Date: 01/13/1999

| AVIATION | | Occurrence Type: Accident | | | | | | | | | | |
|--|--|---------------------------|--|-----------------------------------|--------------|------------|---------------|----------|----------------|----------|------------|------------|
| VETY BOK | Terroe Type | nice Type. Accident | | | | | | | | | | |
| Landing Facility/Approach In Airport Name | ormation | | Airport ID: | Airport Eleva | tion | Run | way Used | Runwa | ay Lengt | th | Runv | way Width |
| LA GUARDIA | | | | | | | | | | " | Num | vay vvidii |
| | | | | | . MSL | | | | | | | |
| Runway Surface Type: | | | | | | | | | | | | |
| Runway Surface Condition: | | | | | | | | | | | | |
| To the forward Americanship | | | | | | | | | | | | |
| Type Instrument Approach: | | | | | | | | | | | | |
| VFR Approach/Landing: | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| Aircraft Information | | | 1 | | | | | | 1 | | | |
| Aircraft Manufacturer Boeing | | | Model 727-2 | /Series 200 | | | | | Serial 2169 | Numbe | er | |
| | | | 1212 | | | | | | 2100 | · I | | |
| Airworthiness Certificate(s): Trans | роп | | | | | | | | | | | |
| Landing Gear Type: Retractable | - Tricycle | | | | | | | | | | | |
| Homebuilt Aircraft? No | Number of Seats: (| 0 | Certifie | ed Max Gross W | /t. | | 194800 | LBS | Numbe | er of Er | Engines: 3 | |
| Engine Type: Turbo Fan | | | Engine Ma | ngine Manufacturer: Model/Series: | | | | | Ra | | Rate | ed Power: |
| - Aircraft Inspection Information | | | | | | | | | | | | |
| Type of Last Inspection | | | Date of Las | st Inspection | | Time Sir | nce Last Insp | ection | | Airfrar | ne To | tal Time |
| Continuous Airworthiness | | | 01/1999 | Hours 518 | | | | | 818 Hours | | | |
| - Emergency Locator Transmitter (| ELT) Information | | | | | | | | | | | |
| ELT Installed? | ELT Operate | ed? | | | ELT | Aided in | n Locating Ac | cident S | Site? | | | |
| Owner/Operator Information | | | | | | | | | | | | |
| Registered Aircraft Owner | | | Street / | Address | | | 22 5 005 | | | | | |
| COMERICA LEASING CORP | | | 29201 TELEGRAPH RD, FLOOR 2 City Stat | | | | | | | te | Zip Code | |
| | | | | | | | | | | | 48034 | |
| Operator of Aircraft | | | Street A | | -ст \ | A/A CL IIA | ICTON CT | CCT | | | | |
| Operator of Aircraft 7337 WEST WASHINGTON STREET AMERICAN TRANS AIR State Zip | | | | | | | | Zip Code | | | | |
| AMERICAN TRANS AIR | | | INDIANAPOLIS | | | | | | | | 46251 | |
| Operator Does Business As: | Operator Does Business As: Operator Designator Code: AMTR | | | | | | | | | | | |
| - Type of U.S. Certificate(s) Held: | | | | | | | | | | | | |
| Air Carrier Operating Certificate(s): | Flag Carrier/Dom | nestic | | | | | | | | | | |
| Operating Certificate: | | | | Operator C | Certific | cate: | | | | | | |
| Regulation Flight Conducted Under | r: Part 121: Air Ca | arrier | | | | | | | | | | |
| Type of Flight Operation Conducted | | | Passenge | r Onlv | | | | | | | | |
| 77 - 3 1 | · | - | | - | | | | | | | | |
| FACTUAL REPORT - AVIATION Page 2 | | | | | | | | | | | | |

NTSB ID: NYC99LA235

Occurrence Date: 01/13/1999

| AVIATION | | | | Occurrence Type: Accident | | | | \dashv | | | | | |
|---|-------------------|----------------|----------------------|---------------------------|-------------------------|---------|---|----------|-----------------------|-----------|-----------|---------------|---------------------|
| First Pilot Information | | | | | | | | | | | | | |
| Name | | | | | | City | State D | | | | | Date of Birth | Age |
| On File | | On File | File On File On File | | | | | | | | | | |
| Sex: M | Seat Occupied | : Left | Prii | ncipal Profes | sion: Civilia | n Pilot | | | Се | rtificate | Numb | er: | • |
| Certificate(s): Airline Transport | | | | | | | | | | | | | |
| Airplane Rating(s): Multi-engine Land; Single-engine Land | | | | | | | | | | | | | |
| Rotorcraft/Glider/LTA: None | | | | | | | | | | | | | |
| Instrument | Rating(s): Airp | lane | | | | | | | | | | | |
| Instructor Rating(s): None | | | | | | | | | | | | | |
| Type Rating | g/Endorsement fo | or Accident/In | ncident Aircra | ft? | | | Current | Biennia | al Flight F | Review? | | | |
| Medical Ce | ert.: Unknown | Medica | al Cert. Statu | s: Unknowr | 1 | | | [| Date of L | ast Med | dical Ex | kam: | |
| | | | | | | | | | | | | | |
| - Flight Tim | ne Matrix | All A/C | This Make and Model | Airplane Single Engine | Airplane Mult-Engine | Night | Night Inst | | strument Simulated | | otorcraft | Glider | Lighter Than Air |
| Total Time | | | | | | | | | | | | | |
| Pilot In Cor | mmand(PIC) | | | | | | | | | | | | |
| Instructor | | | | | | | | | | | | | |
| Last 90 Da | ys | | | | | | | | | | | | |
| Last 30 Da | | | | | | | | | | | | | |
| Last 24 Ho | urs | | | | | | | | | | | | |
| Seatbelt Us | sed? | Shou | lder Harness | Used? | | To | Toxicology Performed? Second Pilot? Yes | | | | | | es |
| Flight Pla | ın/Itinerary | | | | | | | | | | | | |
| | ght Plan Filed: U | nknown | | | | | | | | | | | |
| Departure l | | - | | | | 5 | State Airport Identifier Depa | | | Depart | ture Time | Time Zone | |
| Same as | Accident/Incide | ent Location | | | | | | LGA | | | 0000 | | |
| Destination | 1 | | | | | 5 | State | Airpor | Airport Identifier | | | | |
| Local Flight | | | | | | | | | | | | | |
| Type of Cle | earance: | | | | | · | | | | | | | |
| Type of Air | space: | | | | | | | | | | | | |
| Weather | Information | | | | | | | | | | | | |
| Source of | Briefing: | | | | | | | | | | | | |
| Method of | Briefing: | | | | | | | | | | | | |
| | | | | | | | | | | | | | _ |
| | | | | FACTUAI | L REPORT | - AVIAT | TON | | | | | | Page 3 |

NTSB ID: NYC99LA235

Occurrence Date: 01/13/1999

Occurrence Type: Accident

| | Occurrence Type. Accident | | | | | | | | | | | | |
|---------------|---------------------------|------------|---------|-----------|--------|------------|---------------------------------|-----------|--------------------------|------------|-----------------|--------------|---------|
| Weather | Weather Information | | | | | | | | | | | | |
| WOF ID | Observation Time | Time Zone | WOF | Elevatio | on | WOF Di | WOF Distance From Accident Site | | | | Direction From | n Accident S | ite |
| LGA | 1651 | EST | | 22 Ft. | MSL | | | | 0 NM | 0 Deg. Mag | | | g. Mag. |
| Sky/Lowes | st Cloud Condition: Scat | tered | · | | | 2 | 2000 Ft. AGL | L C | Condition of Light: Dusk | | | | |
| Lowest Ce | illing: Overcast | | 36 | 600 Ft. / | AGL | Visibi | lity: | 9 | SM | Altir | meter: | 30.00 | "Hg |
| Temperatu | ıre: -2 °C | Dew Point: | - | 7 °C | Wind | Direction: | 20 | | | Der | nsity Altitude: | | Ft. |
| Wind Spee | ed: 18 | Gusts: 2 | 21 | | Weath | ner Condti | ions at Accide | ent Site: | : Visual C | ondi | itions | | |
| Visibility (F | RVR): 0 Ft. | Visibility | (RVV) | 0 | SM | Intensity | of Precipitat | tion: Un | nknown | | | | |
| Restriction | s to Visibility: None | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| Type of Pro | ecipitation: None | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| Accident | Information | | | | | | | | | | | | |
| Aircraft Da | mage: None | | Airc | raft Fire | : None | | | А | ircraft Expl | osio | n None | | |
| Classificati | ion: U.S. Registered/U | .S. Soil | | | | | | | | | | | |
| - Injury Su | mmary Matrix | Fatal | Serious | Minor | | None | TOTAL | | | | | | |
| First Pi | ilot | | | | | 1 | 1 | | | | | | |
| Second | d Pilot | | | | | 1 | 1 | | | | | | |
| Studen | nt Pilot | | | | | | | | | | | | |
| Flight I | nstructor | | | | | | | | | | | | |
| Check | Pilot | | | | | | | | | | | | |
| Flight E | Engineer | | | | | 1 | 1 | | | | | | |
| Cabin / | Attendants | | | | | 4 | 4 | | | | | | |
| Other 0 | Crew | | | | | | | | | | | | |
| Passer | ngers | | | | | 153 | 153 | | | | | | |
| - TOTAL A | ABOARD - | | | | | 160 | 160 | | | | | | |
| Other (| Ground | 0 | 1 | | 0 | | 1 | | | | | | |
| - GRANI | O TOTAL - | 0 | 1 | | 0 | 160 | 161 | | | | | | |
| | | | | | | | | | | | | | |

| National Transportation Safety Board | NTSB ID: NYC99LA235 | |
|--|-----------------------------|---|
| National Transportation Safety Board FACTUAL REPORT | Occurrence Date: 01/13/1999 | |
| AVIATION | Occurrence Type: Accident | |
| Administrative Information | • | • |
| Investigator-In-Charge (IIC) | | |
| PAUL R. COX | | |
| Additional Persons Participating in This Accident/Ir | ncident Investigation: | |
| NONE | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |