## Frozen elevators, McDonnell Douglas MD-82, February 5, 1999

Micro-summary: This McDonnell Douglas MD-82 airplane encountered a partial flight control malfunction during takeoff.

Event Date: 1999-02-05 at 1110 AST

Investigative Body: National Transportation Safety Board (NTSB), USA

Investigative Body's Web Site: http://www.ntsb.gov/

## **Cautions:**

- 1. Accident reports can be and sometimes are revised. Be sure to consult the investigative agency for the latest version before basing anything significant on content (e.g., thesis, research, etc).
- 2. Readers are advised that each report is a glimpse of events at specific points in time. While broad themes permeate the causal events leading up to crashes, and we can learn from those, the specific regulatory and technological environments can and do change. Your company's flight operations manual is the final authority as to the safe operation of your aircraft!
- 3. Reports may or may not represent reality. Many many non-scientific factors go into an investigation, including the magnitude of the event, the experience of the investigator, the political climate, relationship with the regulatory authority, technological and recovery capabilities, etc. It is recommended that the reader review all reports analytically. Even a "bad" report can be a very useful launching point for learning.
- 4. Contact us before reproducing or redistributing a report from this anthology. Individual countries have very differing views on copyright! We can advise you on the steps to follow.

Aircraft Accident Reports on DVD, Copyright © 2006 by Flight Simulation Systems, LLC All rights reserved.

www.fss.aero

National Transportation Safety Board	D: ANC99IA02	7	Aircraft Registration Number: N934AS				
FACTUAL REPORT	ence Date: 02/05	5/1999	Most Critical Injury: None				
AVIATION	AVIATION Occurre			Investigated By: NTSB			
Location/Time							
Nearest City/Place	State	Zip Code	Code Local Time				
FAIRBANKS	AK	99709 1110		AST			
Airport Proximity: On Airport	Landing Facility:	•	Direction From Airport:				
Aircraft Information Summary							
Aircraft Manufacturer	Model/Series	3			Type of Aircraft		
McDonnell Douglas	MD-82			Airplane			
Sightseeing Flight: No Air Medical Transport Flight: No							

## Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On February 5, 1999, about 1110 Alaska standard time, the crew of a McDonnell Douglas MD-82 airplane, N934AS, reported a partial flight control malfunction during takeoff from the Fairbanks International Airport, Fairbanks, Alaska. The flight was being conducted under Title 14, CFR Part 121, as a scheduled domestic passenger flight, operated by Alaska Airlines, Inc., as Flight 82. There were no injuries to the two pilots, three flight attendants, or the 133 passengers aboard. Instrument meteorological conditions prevailed, and an instrument flight plan had been filed for the flight to Anchorage, Alaska.

During an interview with the National Transportation Safety Board (NTSB) investigator-in-charge on February 5, the captain stated that during the takeoff roll, the airplane's nose failed to rise as he applied aft control yoke pressure. He stated that when he applied an excessive amount of aft control yoke pressure, the nose rotated slowly, and the airplane assumed the desired pitch angle for takeoff. He said that after he was assured that a positive rate of climb had been established, he declared an in-flight emergency, and continued on to Anchorage for an emergency landing.

The captain said that during the approach and landing in Anchorage, the elevator control felt "sluggish and slow to respond to control inputs." After landing, the airplane was taxied to the gate, and all 138 of the occupants disembarked uneventfully.

Fairbanks International Airport weather observation at the time of the incident consisted of: Sky conditions and ceiling, 400 feet broken, 2,000 feet overcast; visibility, 1/2 statute mile; wind, calm; temperature, minus 47 degrees F.

During a telephone conversation with the National Transportation Safety Board (NTSB) investigator-in-charge on February 6, the director of flight safety for the operator reported that prior to the incident, the incident airplane remained parked at the gate overnight, outside, prior to the incident flight. He added that while the airplane remained in Fairbanks overnight, the outside air temperature went below minus 50 degrees F.

The incident airplane remained in Anchorage for two days following the partial flight control malfunction. While in Anchorage, the airplane underwent an extensive inspection and evaluation of the flight control system, and no flight control anomalies were discovered by company maintenance personnel.

The airplane's flight data recorder (FDR) was removed and shipped to the NTSB's Washington, D.C., laboratory for analysis. The FDR readout showed that during the initial phase of the incident takeoff roll, both elevators remained in a down position. As the takeoff roll progressed and the airspeed approached 150 knots, both elevators responded to the pilot's control column inputs, and the nose of the airplane rotated. The pilot's control column position was not a recorded parameters of the incident airplanes FDR.

TRANSP
National Transportation Safety Board
0 7
FACTUAL REPORT
2
AVIATION

NTSB ID: ANC99IA027

TACLUAL REPORT	Occurrence Date: 02/05/1999					
AVIATION	Occurrence Type: Incident					
Narrative (Continued)	•					
	FACTUAL REPORT - AVIATION	Page 1a				

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: ANC99IA027

Occurrence Date: 02/05/1999

AVIATION	rrence	Туре: І	ncident									
Landing Facility/Approach In	formation											
Airport Name			Airport	ID:	Airport Elevat	ion	Run	way Used	Runwa	vay Length		Runway Width
Fairbanks International			FAI		434 Ft.	MSL	191	₹	5400		(	60
Runway Surface Type: Asphalt							·				•	
Runway Surface Condition: Snowdry												
Type Instrument Approach: NONE												
VFR Approach/Landing: None												
Aircraft Information												
Aircraft Manufacturer McDonnell Douglas				lodel/S MD-82	eries					Serial 4923	Number 5	
Airworthiness Certificate(s): Normal												
Landing Gear Type: Tricycle												
Homebuilt Aircraft? No	Number of Seats:	s: 148 Certified Max Gross Wt. 150500 LBS Number of							er of Engines: 2			
				Engine Manufacturer: Model/Series: JT8D-217							Rated Power: 20850 LBS	
- Aircraft Inspection Information												
Type of Last Inspection			Date of	ate of Last Inspection Time Since Last Inspection					Airframe	e Total Time		
Unknown				Hours							Hours	
- Emergency Locator Transmitter (	ELT) Information											
ELT Installed? No	ELT Operate	ed? No	)			ELT	Aided i	n Locating A	ccident S	ite? No	)	
Owner/Operator Information												
Registered Aircraft Owner			Str	reet Ad	dress Rodney S	Squa	re North	า				
Willmington Trust Comapny			City	City							State	Zip Code
			Stre	Willington DE 19890 Street Address								
Operator of Aircraft						< 689	900 / CO	DDE: SEAC	)Z			
ALASKA AIR GROUP, INC				City SEATTLE						State WA	Zip Code 98168	
Operator Does Business As: ALASKA AIRLINES						_	Oı	perator Desig	gnator Co	ode: AS		100100
- Type of U.S. Certificate(s) Held:												
Air Carrier Operating Certificate(s)	: Flag Carrier/Dom	nestic										
Operating Certificate: Operator Certificate:												
Regulation Flight Conducted Under: Part 121: Air Carrier												
Type of Flight Operation Conducted: Scheduled; Domestic; Passenger Only												
	]	FACTU	UAL R	EPOR	T - AVIATI	ON						Page 2

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: ANC99IA027

Occurrence Date: 02/05/1999

TACIDAL REFORT				Coourience Bate. 02/03/1393									
AVIATION				Occurrence Type: Incident									
First Pilo	t Information												
Name						City			S	tate	Date of Birth	Age	
On File						On File		On File On File 5					
Sex: M	Seat Occupied	Prin	cipal Profes	n Pilot			Certific	ate Num	ber: On File				
Certificate(s): Airline Transport													
Airplane Rating(s): Multi-engine Land													
Rotorcraft/Glider/LTA: None													
Instrument	Rating(s): Airpl	lane											
Instructor Rating(s): Airplane Multi-engine; Instrument Airplane													
Type Ratin	g/Endorsement fo	or Accident/In	cident Aircrat	ft? Yes			Current	Biennial Fli	ght Revi	ew?			
Medical Ce	ert.: Class 1	Medica	l Cert. Status	: Valid Me	dicalno w	aivers/lir	n.	Date	of Last I	Medical I	Exam: 11/1998		
		'											
- Flight Tim	ne Matrix	Matrix  All A/C  This Make Airplane Airplane and Model Single Engine Mult-Engine				Night	Instrument Actual Simu		ulated	Rotorcraft	Glider	Lighter Than Air	
Total Time		15070	8444										
Pilot In Cor	mmand(PIC)												
Instructor													
Last 90 Da	ys	156											
Last 30 Da	-												
Last 24 Ho	urs	<u> </u>				<del></del>							
Seatbelt Us	sed? Yes	Shou	lder Harness	Used? Yes		Т	oxicology F	erformed?	No	S	Second Pilot? Ye	es	
=======================================													
	n/Itinerary ght Plan Filed: IF	D											
Departure I		K				T	State	Airport Ide	ntifier	Dens	artura Tima	Time Zone	
	Accident/Incide	ent Location				,	State	FAI	munei	Departure Time Time		Time Zone	
Destination	n						State	Airport Ide	ntifier				
ANCHORAGE							λK	ANC	ANC				
Type of Cle	earance: IFR					•							
Type of Airspace: Class C													
Weather	Information												
Source of	Briefing: Compa	any											
Method of	Briefing: In Pers	son											
	FACTUAL REPORT - AVIATION Page 3												
					_	_							

National Transportation Safety Board FACTUAL REPORT

NTSB ID: ANC99IA027

Occurrence Date: 02/05/1999

AYAHON			0	Occurrence Type: Incident									
Weather	Information												
WOF ID	Observation Time	Time Zone	WOR	F Elevati	on	WOF Di	WOF Distance From Accident Site				Direction From	Accident Sit	е
FAI	1052	ADT		0 Ft.	MSL				0 NM		0 Deg. Mag.		
Sky/Lowes	st Cloud Condition: Unkn	Cloud Condition: Unknown Ft. AGL Condition of Light: Day											
Lowest Ce	eiling: Broken			400 Ft.	AGL	Visibi	lity:	0.5	SM	Altii	meter:	29.00	"Hg
Temperatu	ure: -44 °C I	Dew Point:		°C	Wind	Direction:				Der	nsity Altitude:		Ft.
Wind Spee	ed:	Gusts:			Weatl	ner Condti	ons at Accid	dent Si	ite: Instrum	ent C	Conditions		
Visibility (R	RVR): 0 Ft.	Visibility	(RVV)	0	SM	Intensity	of Precipita	ation:					
Restriction	ns to Visibility: Fog	•											
Type of Pre	ecipitation: None												
Accident	Information												
Aircraft Dar	mage: None		Air	craft Fire	 ∍: None	;			Aircraft Exp	losio	n None		
Classificati	ion: U.S. Registered/U	.S. Soil											
- Injury Sui	mmary Matrix	Fatal	Serious	Mino	r	None	TOTAL						
First Pil	ilot					1	1	]					
Second	d Pilot					1	1	]					
Studen	nt Pilot							1					
Flight Iı	nstructor							1					
Check I	Pilot							1					
Flight E	Engineer							1					
Cabin A	Attendants					3	3	]					
Other C	Crew							]					
Passen	ngers					133	133	1					
- TOTAL A	ABOARD -					138	138	1					
Other G	Ground	0	(	0	0		0	1					
- GRAND	O TOTAL -	0		0	0	138	138	1					
				•	•								

National Transportation Safety Board

## FACTUAL REPORT AVIATION

NTSB ID: ANC99IA027

Occurrence Date: 02/05/1999

Occurrence Type: Incident

Administrative	Int	forms	ation
Administrative			atioi

Investigator-In-Charge (IIC)

CLINTON O. JOHNSON

Additional Persons Participating in This Accident/Incident Investigation:

HARRY C GILSON Aviation Inspector Federal Aviation Administration 4510 West International Airport Road Anchorage, AK 99502