
In-flight smoke and fire, Douglas DC-9-32, August 8, 2000

Micro-summary: This Douglas DC-9-32 executed an emergency landing due to an in-flight fire and smoke in the cockpit.

Event Date: 2000-08-08 at 1544 EDT

Investigative Body: National Transportation Safety Board (NTSB), USA

Investigative Body's Web Site: <http://www.nts.gov/>

Cautions:

1. Accident reports can be and sometimes are revised. Be sure to consult the investigative agency for the latest version before basing anything significant on content (e.g., thesis, research, etc).
 2. Readers are advised that each report is a glimpse of events at specific points in time. While broad themes permeate the causal events leading up to crashes, and we can learn from those, the specific regulatory and technological environments can and do change. ***Your company's flight operations manual is the final authority as to the safe operation of your aircraft!***
 3. Reports may or may not represent reality. Many many non-scientific factors go into an investigation, including the magnitude of the event, the experience of the investigator, the political climate, relationship with the regulatory authority, technological and recovery capabilities, etc. It is recommended that the reader review all reports analytically. Even a "bad" report can be a very useful launching point for learning.
 4. Contact us before reproducing or redistributing a report from this anthology. Individual countries have very differing views on copyright! We can advise you on the steps to follow.
-

 National Transportation Safety Board FACTUAL REPORT AVIATION		NTSB ID: DCA00MA079		Aircraft Registration Number: N838AT	
		Occurrence Date: 08/08/2000		Most Critical Injury: Minor	
		Occurrence Type: Accident		Investigated By: NTSB	
Location/Time					
Nearest City/Place GREENSBORO		State NC	Zip Code	Local Time 1544	Time Zone EDT
Airport Proximity: Off Airport/Airstrip		Distance From Landing Facility:		Direction From Airport:	
Aircraft Information Summary					
Aircraft Manufacturer Douglas		Model/Series DC-9-32		Type of Aircraft Airplane	
Sightseeing Flight: No			Air Medical Transport Flight: No		
Narrative					
Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:					
<p>On August 8, 2000, about 1544 eastern daylight time, the flight crew of AirTran Airways flight 913, a McDonnell Douglas DC-9-32, N838AT, executed an emergency landing at Greensboro Piedmont-Triad International Airport (GSO) shortly after declaring an emergency due to an in-flight fire and smoke in the cockpit. An emergency evacuation was performed. Of the 58 passengers and 5 crewmembers on board, 3 crewmembers and 5 passengers received minor injuries from smoke inhalation. Five passengers and one ground crewmember received minor injuries during the evacuation. The airplane sustained substantial fire, heat, and smoke damage. The flight was operating on an instrument flight rules flight plan under the provisions of 14 Code of Federal Regulations Part 121 as a regularly scheduled passenger flight from Greensboro, North Carolina, to Atlanta, Georgia. Visual meteorological conditions prevailed at the time of the accident.</p>					
AIRPLANE INFORMATION					
<p>N838AT, a DC-9-32, serial number 47442, was delivered new to Turkish Airlines on August 24, 1970. It was registered to ValuJet on March 7, 1995 (ValuJet was acquired by AirTran Airways in 1997).</p>					
FIRE DAMAGE					
<p>Examination of the airplane revealed severe smoke and heat damage around the electric power center (EPC) and within the cockpit. Removal of the forward and aft EPC panels revealed heavy sooting, melted wire insulation, visibly broken wires, and localized heat damage. The lowest point of the fire damage on the cabin (aft) side of the EPC was in the upper compartment where it was noted that the aluminum stanchion brace that runs the length of that compartment was destroyed along with the AC bus feeder wires and numerous other airplane wiring bundles. No fire damage was noted in the lower aft compartment. The lowest point of the fire damage was on the cockpit side of the EPC, behind the lower right access panel where the AC ground service tie relay and the right and left heat exchanger cooling fan relays were located. The location of the fire damage is consistent with it being the point of origin for the fire.</p>					
TESTS AND RESEARCH					
Relay Examination and Evaluation					
<p>Examination of the relays located in the area of the fire origin (R2-53 and R2-54) revealed that R2-53, the left heat exchanger cooling fan relay, was severely heat damaged, as were the other relays in this area. However, only the R2-53 relay had loose terminal studs and several holes that had burned through the relay housing. The largest of the burn holes observed in the R2-53 relay were on the terminal "A" side directly above the wiring bundles.</p>					
<p>Removal of the R2-53 relay cover revealed that none of the rotating contacts, or armatures,</p>					
FACTUAL REPORT - AVIATION					

National Transportation Safety Board

FACTUAL REPORT

AVIATION

NTSB ID: DCA00MA079

Occurrence Date: 08/08/2000

Occurrence Type: Accident

Narrative (Continued)

were touching the stationary contacts, indicating that the relay was in the de-energized, or open, condition. This finding suggests that, initially, the relay functioned properly by returning the rotating armature to the open position after takeoff.

Disassembly of the relay revealed that the floor between the housing upper cavity and lower cavity was heavily heat damaged. Arc damage extended around three sides of the relay; only the side containing the "C" terminals remained intact. According to the manufacturer, Leach International Corporation, the damage to the relay housing was consistent with a phase-to-phase arc between terminals "A2" and "B2" of the relay. Disassembly of the relay also revealed that one of the wires that passes between the two coils in the lower housing adjacent to the armature shaft exhibited insulation damage. No evidence was observed to suggest that the wire arced or overheated, indicating that the wire did not cause or contribute to a short in the relay.

Relay Repairs

Visual examination and disassembly of the R2-53 relay revealed numerous repairs that did not conform to Leach production standards. For example, the baseplate and coil assembly time-delay circuit were attached with four slotted screws that exhibited mechanical damage and that did not have the typical coating of sealant, some of the diodes on the time-delay circuit board appeared to be different than those used by Leach during production, nonstandard shims were installed between the relay housing and the stationary contact, and nonstandard, pre-drilled two-hole washers were found installed below the contact carrier assembly.

According to Leach, no overhaul or component maintenance manual has been released to outside repair stations or vendors for repair of this part. Leach representatives reported that their facility does not overhaul this relay but might do minor repairs as part of warranty work, such as changing the time-delay circuit board. Additionally, according to Leach, any repairs performed at the facility would require stamping the outside of the relay housing with the letter "R." No such marking was found anywhere on the R2-53 relay housing.

Disassembly of the R2-54 relay revealed many of the same nonconforming repairs noted during the examination of the R2-53 relay. During the examination of the R2-54 relay, an alphanumeric stamp, "JNR 11-17-78," was discovered on the underside of the relay cover. Leach indicated that this stamp is not a Leach repair or manufacturing mark. The repair date code indicates that the repair was performed while the aircraft was owned and operated by Turkish Airlines.

Circuit Breakers Examination and Evaluation

During the on-scene portion of the investigation, three of the four circuit breakers in the left heat exchanger cooling fan were found in the tripped position. To determine why only three of the four circuit breakers tripped, all four were submitted to the Materials Integrity Branch at Wright-Patterson Air Force Base, Dayton, Ohio, for further examination. The circuit breakers were visually examined and were subjected to an insulation resistance measurement, a contact resistance test, a voltage drop test, and a calibration test (which measured minimum and maximum ultimate trip times). Testing and examination determined that the circuit breaker that did not trip exhibited no anomalies that would prevent normal operation, met all specifications required for the selected tests, and operated properly during the calibration test. Although this circuit breaker appeared to have functioned properly during testing, the lab report noted that, as a thermal device, the circuit breaker is designed to trip when a sustained current overload exists and that it is possible during the event that intermittent arcing or a resistive short occurred or that the circuit opened before the breaker reached a temperature sufficient to trip the device.

ADDITIONAL INFORMATION

As a result of this accident, AirTran inspected its entire DC-9 fleet for anomalies in the R2-53 and R2-54 relays. Five relays were removed from service due to loose terminal studs. A DC-9 fleet campaign was conducted to inspect R2-53 and R2-54 relays and to determine if relay

National Transportation Safety Board

FACTUAL REPORT

AVIATION

NTSB ID: DCA00MA079

Occurrence Date: 08/08/2000

Occurrence Type: Accident

Narrative (Continued)

degradation was time-related and whether a hard-time inspection was warranted. The results of the survey indicate that a hard-time service limit is not warranted; however, several relays showed clear indications that unauthorized repairs had been performed, similar to those apparently performed on the accident R2-53 relay.

The Safety Board also learned during its investigation of this accident that neither flight attendant on board flight 913 attempted to locate the source of the smoke in the cabin or to use any of the firefighting equipment available to them. It was also learned that AirTran's flight attendant training program does not include any drill involving hidden fires but does include a drill that uses a visible, open flame. Based on this accident (and others involving in-flight fires), the Safety Board issued five safety recommendations to the FAA on January 4, 2002, regarding improved crewmember training for fighting in-flight fires.

The Safety Board's investigation also revealed that after donning his oxygen mask, the first officer removed it to address the passengers on the public address system, exposing himself to the smoke and the potential for incapacitation. He reported in a postaccident interview that he continued to feel the effects of the smoke after he replaced his mask. The first officer was treated for smoke inhalation after evacuating the airplane.

 National Transportation Safety Board FACTUAL REPORT AVIATION		NTSB ID: DCA00MA079				
		Occurrence Date: 08/08/2000				
		Occurrence Type: Accident				
Landing Facility/Approach Information						
Airport Name PIEDMONT TRIAD INTERNATIONAL		Airport ID: GSO	Airport Elevation Ft. MSL	Runway Used 0	Runway Length	Runway Width
Runway Surface Type: Asphalt						
Runway Surface Condition: Dry						
Type Instrument Approach: NONE						
VFR Approach/Landing: Precautionary Landing						
Aircraft Information						
Aircraft Manufacturer Douglas		Model/Series DC-9-32		Serial Number		
Airworthiness Certificate(s): Transport						
Landing Gear Type: Retractable - Tricycle						
Homebuilt Aircraft? No		Number of Seats: 119		Certified Max Gross Wt. LBS		Number of Engines: 2
Engine Type: Turbo Jet		Engine Manufacturer: Pratt & Whitney		Model/Series: JT8D		Rated Power: 14500 LBS
- Aircraft Inspection Information						
Type of Last Inspection Unknown		Date of Last Inspection		Time Since Last Inspection Hours		Airframe Total Time Hours
- Emergency Locator Transmitter (ELT) Information						
ELT Installed?		ELT Operated?		ELT Aided in Locating Accident Site?		
Owner/Operator Information						
Registered Aircraft Owner		Street Address				
		City		State	Zip Code	
Operator of Aircraft AIRTRAN AIRLINES INC		Street Address 9955 AIR TRAN BLVD				
		City ORLANDO		State FL	Zip Code 32827	
Operator Does Business As:				Operator Designator Code: VJ6A		
- Type of U.S. Certificate(s) Held:						
Air Carrier Operating Certificate(s): Flag Carrier/Domestic						
Operating Certificate:			Operator Certificate:			
Regulation Flight Conducted Under: Part 121: Air Carrier						
Type of Flight Operation Conducted: Scheduled; Domestic; Passenger Only						

 <p>National Transportation Safety Board FACTUAL REPORT AVIATION</p>	NTSB ID: DCA00MA079
	Occurrence Date: 08/08/2000
	Occurrence Type: Accident

First Pilot Information

Name On File	City	State	Date of Birth On File	Age 51
-----------------	------	-------	--------------------------	-----------

Sex: M	Seat Occupied: Left	Principal Profession: Civilian Pilot	Certificate Number: On File
--------	---------------------	--------------------------------------	-----------------------------

Certificate(s): Airline Transport; Commercial

Airplane Rating(s): Multi-engine Land; Single-engine Land

Rotorcraft/Glider/LTA: Helicopter

Instrument Rating(s): Airplane; Helicopter

Instructor Rating(s):

Type Rating/Endorsement for Accident/Incident Aircraft? Yes	Current Biennial Flight Review? 04/2000
---	---

Medical Cert.: Class 1	Medical Cert. Status: Valid Medical--no waivers/lim.	Date of Last Medical Exam: 06/2000
------------------------	--	------------------------------------

- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Multi-Engine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	22000	15000								
Pilot In Command(PIC)		10000								
Instructor										
Last 90 Days										
Last 30 Days										
Last 24 Hours										

Seatbelt Used? Yes	Shoulder Harness Used? Yes	Toxicology Performed?	Second Pilot?
--------------------	----------------------------	-----------------------	---------------

Flight Plan/Itinerary

Type of Flight Plan Filed: IFR

Departure Point Same as Accident/Incident Location	State	Airport Identifier	Departure Time 0000	Time Zone
---	-------	--------------------	------------------------	-----------

Destination ATLANTA	State GA	Airport Identifier ATL	
------------------------	-------------	---------------------------	--

Type of Clearance:

Type of Airspace:

Weather Information

Source of Briefing:

Method of Briefing:

 <p>National Transportation Safety Board FACTUAL REPORT AVIATION</p>	NTSB ID: DCA00MA079
	Occurrence Date: 08/08/2000
	Occurrence Type: Accident

Weather Information					
WOF ID	Observation Time	Time Zone	WOF Elevation Ft. MSL	WOF Distance From Accident Site NM	Direction From Accident Site Deg. Mag.
Sky/Lowest Cloud Condition: Clear			Ft. AGL	Condition of Light: Not Reported	
Lowest Ceiling: None		Ft. AGL	Visibility: 10	SM	Altimeter: "Hg
Temperature: °C	Dew Point: °C	Wind Direction:		Density Altitude: Ft.	
Wind Speed: Calm	Gusts:	Weather Conditions at Accident Site: Visual Conditions			
Visibility (RVR): 0 Ft.	Visibility (RVV) 0	SM	Intensity of Precipitation:		
Restrictions to Visibility:					
Type of Precipitation: None					

Accident Information		
Aircraft Damage: Substantial	Aircraft Fire: In-flight	Aircraft Explosion: None

Classification: U.S. Registered/U.S. Soil					
- Injury Summary Matrix	Fatal	Serious	Minor	None	TOTAL
First Pilot				1	1
Second Pilot			1		1
Student Pilot					
Flight Instructor					
Check Pilot					
Flight Engineer					
Cabin Attendants			2	1	3
Other Crew					
Passengers			10	48	58
- TOTAL ABOARD -			13	50	63
Other Ground	0	0	0		0
- GRAND TOTAL -	0	0	13	50	63

National Transportation Safety Board

FACTUAL REPORT

AVIATION



NTSB ID: DCA00MA079

Occurrence Date: 08/08/2000

Occurrence Type: Accident

Administrative Information

Investigator-In-Charge (IIC)

Lorenda Ward

Additional Persons Participating in This Accident/Incident Investigation:

ROBERT HENLEY

AAI-100