
Turbulence on descent, Boeing 777-223, February 25, 2003

Micro-summary: This Boeing 777-223 encountered turbulence on descent, injuring two flight attendants.


Event Date: 2003-02-25 at 1616 EST

Investigative Body: National Transportation Safety Board (NTSB), USA

Investigative Body's Web Site: <http://www.nts.gov/>

Cautions:

1. Accident reports can be and sometimes are revised. Be sure to consult the investigative agency for the latest version before basing anything significant on content (e.g., thesis, research, etc).
 2. Readers are advised that each report is a glimpse of events at specific points in time. While broad themes permeate the causal events leading up to crashes, and we can learn from those, the specific regulatory and technological environments can and do change. ***Your company's flight operations manual is the final authority as to the safe operation of your aircraft!***
 3. Reports may or may not represent reality. Many many non-scientific factors go into an investigation, including the magnitude of the event, the experience of the investigator, the political climate, relationship with the regulatory authority, technological and recovery capabilities, etc. It is recommended that the reader review all reports analytically. Even a "bad" report can be a very useful launching point for learning.
 4. Contact us before reproducing or redistributing a report from this anthology. Individual countries have very differing views on copyright! We can advise you on the steps to follow.
-

		NTSB ID: MIA03LA067		Aircraft Registration Number: N790AN	
		Occurrence Date: 02/25/2003		Most Critical Injury: Serious	
		Occurrence Type: Accident		Investigated By: NTSB	
Location/Time					
Nearest City/Place Miami		State FL	Zip Code 33159	Local Time 1616	Time Zone EST
Airport Proximity: Off Airport/Airstrip		Distance From Landing Facility:		Direction From Airport:	
Aircraft Information Summary					
Aircraft Manufacturer Boeing		Model/Series 777-223		Type of Aircraft Airplane	
Sightseeing Flight: No			Air Medical Transport Flight: No		
Narrative					
<p>Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:</p> <p>On February 25, 2003, about 1616 eastern standard time, a Boeing 777-223, N790AN, operated by American Airlines Inc. (Flt AA1614), as a Title 14 CFR Part 121 scheduled domestic flight, encountered turbulence while on descent to Miami International Airport, Miami, Florida. Visual meteorological conditions prevailed. An instrument flight rules flight plan was filed. The airplane was not damaged. The two airline transport-rated pilots, six flight attendants, and 123 passengers reported no injuries. Two flight attendants reported serious injuries. The flight had departed from the Dallas-Fort Worth International Airport, Arlington, Texas en route to Miami, Florida, at 1356 eastern standard time.</p> <p>According to the captain, while descending into Miami, they began deviating well south of a few small cumulous developments. The first officer was flying the airplane at the time of the event. They had begun reducing speed to turbulence penetration prior to encountering a few pockets of light chop at about FL240. The captain gave a public address system announcement to the flight attendants and passengers leaving FL180, asking that the cabin be prepared for landing early, due to possible chop during our approach. Air Traffic Control was advised of the speed reductions, and subsequently caused traffic behind them to also have to slow. As they approached the tops of a very thin cloud layer at about 11,000 feet, descending to 10,000 feet, at a speed of about 260 knots, they encountered a very brief pocket of moderate chop. Several minutes after the event, the number one flight attendant, advised the captain that two of the flight attendants in the aft part of the airplane had been injured during the turbulence event. She requested that medical assistance meet the airplane.</p> <p>According to interviews with the cabin crew, the seatbelt sign was on, they were in the process of securing the cabin for landing, and the purser had made the announcement for passengers to prepare for landing right after the captain's pre-landing announcement. During the turbulence encounter, most of the flight attendants reported being lifted off their feet, and thrown to the floor. Three of the flight attendants commented that they were able to steady themselves with hand holds which kept them from falling. Following the turbulence encounter, two flight attendants noted a passenger exiting a lavatory uninjured. A few passengers had left their seats following the turbulence encounter to assist the injured flight attendants. After arriving at the gate, paramedics boarded the airplane, then the passengers were deplaned, and two flight attendants were transported to the hospital by ambulance.</p> <p>Meteorological information obtained by an NTSB Meteorologist showed a convective SIGMET was valid for Florida and coastal waters at the time of the turbulence encounter. The convective SIGMET was issued in response to a developing area of thunderstorms moving from 260 degrees at 10 knots with tops extending to 32,000 feet. Radar images from the Miami Weather Surveillance Radar (WSR-88D) identified multiple storm cells in the area at the time of the turbulence encounter. The radar data indicated that the core intensity of these cells was strong to intense (40 to 50 dBZ). A radar image taken about the time of the turbulence encounter shows the airplanes path came about</p>					
FACTUAL REPORT - AVIATION					
Page 1					

National Transportation Safety Board

FACTUAL REPORT

AVIATION

NTSB ID: MIA03LA067

Occurrence Date: 02/25/2003

Occurrence Type: Accident


Narrative (Continued)


five nautical miles from the core of one cell and three nautical miles from the core of a second cell.

The digital flight data recorder (DFDR) was removed from the airplane after the accident and sent to the NTSB Vehicles Recorder Laboratory, Washington, D.C. The recorder was in good condition, and the data were extracted normally from the recorder. The DFDR was downloaded to hard disk using NTSB readout equipment. The acquired accident data were verified for accuracy by examining take-off, cruise, and landing performance of the aircraft previously recorded on the medium. The data were found to be consistent with the normal operation of the aircraft.

The DFDR recording contained approximately 98 hours of data. The accident flight was the third from the end of the recording and began at approximately Subframe Reference Number (SRN) 292056. The duration of the incident flight was approximately 2 hours 48 minutes. The turbulence event occurred approximately 2 hours 20 minutes into the flight at approximately SRN 298456, while the aircraft was descending through an altitude of approximately 12,836 feet, on a heading of 115 degrees. During this event, the data shows the aircraft with a 2.04 g vertical acceleration load and 6 degrees of left roll. The pitch changed from -0.4 at SRN 298456 to -2.1 at SRN 298457. The autopilot remained on throughout the event and was turned off at SRN 298781. The DFDR was returned by NTSB to American Airlines on July 12, 2004.

Recorded radar data from the FAA Miami Air Route Traffic Control Center show that at about the time of the turbulence encounter the airplane was at position 25 degrees 56 minutes 50 seconds North latitude and 81 degrees 15 minutes 9 seconds West longitude, or about bearing 280 degrees at 53 nautical miles from Miami International Airport.

 National Transportation Safety Board FACTUAL REPORT AVIATION		NTSB ID: MIA03LA067			
		Occurrence Date: 02/25/2003			
		Occurrence Type: Accident			
Landing Facility/Approach Information					
Airport Name	Airport ID:	Airport Elevation	Runway Used	Runway Length	Runway Width
Miami International	MIA	Ft. MSL	NA		
Runway Surface Type: Unknown					
Runway Surface Condition: Unknown					
Type Instrument Approach: Unknown					
VFR Approach/Landing: Unknown					
Aircraft Information					
Aircraft Manufacturer		Model/Series		Serial Number	
Boeing		777-223		30251	
Airworthiness Certificate(s): Transport					
Landing Gear Type: Retractable - Tricycle					
Homebuilt Aircraft? No	Number of Seats: 310	Certified Max Gross Wt.	656000 LBS	Number of Engines: 2	
Engine Type:	Engine Manufacturer:	Model/Series:	Rated Power:		
Turbo Fan	Rolls-Royce	Trent 892-17	93400 LBS		
- Aircraft Inspection Information					
Type of Last Inspection	Date of Last Inspection	Time Since Last Inspection	Airframe Total Time		
Continuous Airworthiness	02/2003	16 Hours	9809 Hours		
- Emergency Locator Transmitter (ELT) Information					
ELT Installed? No	ELT Operated? No	ELT Aided in Locating Accident Site? No			
Owner/Operator Information					
Registered Aircraft Owner		Street Address			
AMERICAN AIRLINES INC		4333 Amon Carter Blvd. 5569			
		City	State	Zip Code	
		Fort Worth	TX	76155	
Operator of Aircraft		Street Address			
Same as Reg'd Aircraft Owner		Same as Reg'd Aircraft Owner			
		City	State	Zip Code	
Operator Does Business As:			Operator Designator Code: AALA		
- Type of U.S. Certificate(s) Held:					
Air Carrier Operating Certificate(s): Flag Carrier/Domestic					
Operating Certificate:			Operator Certificate:		
Regulation Flight Conducted Under: Part 121: Air Carrier					
Type of Flight Operation Conducted: Scheduled; Domestic; Passenger Only					
FACTUAL REPORT - AVIATION					

 <p>National Transportation Safety Board FACTUAL REPORT AVIATION</p>	NTSB ID: MIA03LA067
	Occurrence Date: 02/25/2003
	Occurrence Type: Accident

First Pilot Information

Name On File	City On File	State On File	Date of Birth On File	Age 54
-----------------	-----------------	------------------	--------------------------	-----------

Sex: M	Seat Occupied: Left	Principal Profession: Civilian Pilot	Certificate Number: On File
--------	---------------------	--------------------------------------	-----------------------------

Certificate(s): Airline Transport; Flight Instructor

Airplane Rating(s): Multi-engine Land; Single-engine Land

Rotorcraft/Glider/LTA: None

Instrument Rating(s): Airplane

Instructor Rating(s): Airplane Multi-engine; Airplane Single-engine

Type Rating/Endorsement for Accident/Incident Aircraft? Yes	Current Biennial Flight Review?
-------------------------------------------------------------	---------------------------------

Medical Cert.: Class 1	Medical Cert. Status: Valid Medical--no waivers/lim.	Date of Last Medical Exam: 01/2003
------------------------	------------------------------------------------------	------------------------------------

- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Multi-Engine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time		974								
Pilot In Command(PIC)										
Instructor										
Last 90 Days	221	221		221						
Last 30 Days	81	81		81						
Last 24 Hours	7	7		7						

Seatbelt Used? Yes	Shoulder Harness Used? Yes	Toxicology Performed? No	Second Pilot? Yes
--------------------	----------------------------	--------------------------	-------------------

Flight Plan/Itinerary

Type of Flight Plan Filed: IFR

Departure Point Arlington	State TX	Airport Identifier KDFW	Departure Time 1356	Time Zone EST
------------------------------	-------------	----------------------------	------------------------	------------------

Destination Same as Accident/Incident Location	State	Airport Identifier KMIA	
---------------------------------------------------	-------	----------------------------	--


Type of Clearance: IFR

Type of Airspace: Class E

Weather Information

Source of Briefing: Company


Method of Briefing: In Person

 <p>National Transportation Safety Board FACTUAL REPORT AVIATION</p>	NTSB ID: MIA03LA067
	Occurrence Date: 02/25/2003
	Occurrence Type: Accident

Weather Information					
WOF ID	Observation Time	Time Zone	WOF Elevation	WOF Distance From Accident Site	Direction From Accident Site
KMIA	1556	EST	8 Ft. MSL	53 NM	100 Deg. Mag.
Sky/Lowest Cloud Condition: Few			2500 Ft. AGL	Condition of Light: Day	
Lowest Ceiling: Broken		9500 Ft. AGL		Visibility: 10 SM	Altimeter: 29.99 "Hg
Temperature: 24 °C	Dew Point: 21 °C	Wind Direction: 70		Density Altitude: 12000 Ft.	
Wind Speed: 8	Gusts:	Weather Conditions at Accident Site: Visual Conditions			
Visibility (RVR): Ft.	Visibility (RVV) SM	Intensity of Precipitation:			
Restrictions to Visibility: None					
Type of Precipitation: None					

Accident Information		
Aircraft Damage: None	Aircraft Fire: None	Aircraft Explosion: None

Classification: U.S. Registered/U.S. Soil					
- Injury Summary Matrix	Fatal	Serious	Minor	None	TOTAL
First Pilot				1	1
Second Pilot				1	1
Student Pilot					
Flight Instructor					
Check Pilot					
Flight Engineer					
Cabin Attendants		2		6	8
Other Crew					
Passengers				123	123
- TOTAL ABOARD -		2		131	133
Other Ground					
- GRAND TOTAL -		2		131	133

 National Transportation Safety Board FACTUAL REPORT AVIATION	NTSB ID: MIA03LA067	
	Occurrence Date: 02/25/2003	
	Occurrence Type: Accident	

Administrative Information

Investigator-In-Charge (IIC)

Jeffrey L. Kennedy

Additional Persons Participating in This Accident/Incident Investigation:

Linda Webb
FAA FSDO
8600 NW 36th Street
Miami, FL 33166

Rick Howes
Boeing Aircraft Company
535 Garden Ave.
Renton, WA 98055

Penny Pollard
American Airlines
4601 Highway 360
Fort Worth, TX 76155

Joann Matley
Association of Professional Flight Attendants
1004 Eules Blvd.
Eules, TX 76040