
Ground collision with tug, McDonnell Douglas MD-88, April 22, 2003

Micro-summary: This McDonnell Douglas MD-88 collided with a tug during pushback.

Event Date: 2003-04-22 at 1252 MDT


Investigative Body: National Transportation Safety Board (NTSB), USA

Investigative Body's Web Site: <http://www.nts.gov/>

Cautions:

1. Accident reports can be and sometimes are revised. Be sure to consult the investigative agency for the latest version before basing anything significant on content (e.g., thesis, research, etc).
 2. Readers are advised that each report is a glimpse of events at specific points in time. While broad themes permeate the causal events leading up to crashes, and we can learn from those, the specific regulatory and technological environments can and do change. ***Your company's flight operations manual is the final authority as to the safe operation of your aircraft!***
 3. Reports may or may not represent reality. Many many non-scientific factors go into an investigation, including the magnitude of the event, the experience of the investigator, the political climate, relationship with the regulatory authority, technological and recovery capabilities, etc. It is recommended that the reader review all reports analytically. Even a "bad" report can be a very useful launching point for learning.
 4. Contact us before reproducing or redistributing a report from this anthology. Individual countries have very differing views on copyright! We can advise you on the steps to follow.
-

Aircraft Accident Reports on DVD, Copyright © 2006 by Flight Simulation Systems, LLC
All rights reserved.
www.fss.aero

 National Transportation Safety Board FACTUAL REPORT AVIATION		NTSB ID: DEN03FA070		Aircraft Registration Number: N974DL	
		Occurrence Date: 04/22/2003		Most Critical Injury: Minor	
		Occurrence Type: Accident		Investigated By: NTSB	
Location/Time					
Nearest City/Place Denver	State CO	Zip Code 80249	Local Time 1252	Time Zone MDT	
Airport Proximity: On Airport		Distance From Landing Facility: 1		Direction From Airport:	
Aircraft Information Summary					
Aircraft Manufacturer McDonnell Douglas		Model/Series MD-88		Type of Aircraft Airplane	
Sightseeing Flight: No			Air Medical Transport Flight: No		
Narrative					
Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:					
HISTORY OF FLIGHT					
<p>On April 22, 2003, at 1252 mountain daylight time, a McDonnell Douglas MD-88, N974DL, owned by Wilmington Trust Company Trustee, Wilmington, Delaware, and operated by Delta Air Lines, Atlanta, Georgia, as Delta flight 964, was substantially damaged when it struck a tug during pushback at Denver International Airport (DEN), Denver, Colorado. The airline transport certificated captain, airline transport certificated first officer, two flight attendants, and 56 passengers were not injured; however, one flight attendant received minor injuries. Visual meteorological conditions prevailed. The scheduled domestic passenger flight was being conducted on an instrument flight rules flight plan under the provisions of Title 14 CFR Part 121. The flight, to Cincinnati, Ohio, was originating at the time of the accident.</p>					
<p>According to Delta Air Lines, the airplane arrived in Denver at 0951 as Delta flight 1185. Delta Flight 964 was scheduled to depart at 1100, but was delayed due to the previous flight crews' report of a take off slat warning light indication problem. A maintenance check was completed and pushback for flight 964 occurred at 1206.</p>					
<p>According to data obtained by the airplane's cockpit voice recorder (CVR), at 1224, while the crew was completing the pre-take off checks during the taxi, the captain reported another take off slat warning light indication problem. Delta maintenance requested that the captain return the airplane to the gate so maintenance personnel could re-examine the fault. If possible, maintenance could "placard" the minimum equipment list (MEL) item so the flight could continue. The airplane arrived back at the gate at 1239.</p>					
<p>At 1241, a Delta maintenance technician boarded the airplane to assess the problem. He stated to the captain that "were gonna [sic] have to mess up with your takeoff condition here and you know after we do this, you're not supposed to move anything." The captain stated "right." During the maintenance check for the slat indication problem, the procedures, as identified in MD-88 MEL 27-00-37, state that "either or both" engine throttles must be advanced to verify the operation of the slat takeoff warning horn. The operation of the system was verified and the slats were set in the takeoff configuration. During the entire maintenance check, the captain and first officer remained seated.</p>					
<p>At 1251, following the completion of the second maintenance check, the first officer called for and received pushback clearance. The engines were started during pushback, and the captain stated that "prior to the engine start sequence, I did not direct re-accomplishment of the before start checklist." The captain said "the pushback and initial stages of the engine start sequence appeared normal." However, shortly after engine start and with the tug still attached, the airplane began to move forward under its own power. At that time, the captain noticed that the throttles were still advanced. The captain and first officer both reached to pull the engine throttles back to idle, but</p>					
FACTUAL REPORT - AVIATION					
					Page 1

National Transportation Safety Board

FACTUAL REPORT

AVIATION

NTSB ID: DEN03FA070

Occurrence Date: 04/22/2003

Occurrence Type: Accident

Narrative (Continued)

the airplane had moved forward enough to cause the tug and tow bar to jackknife to the left. The captain shut down the engines, secured the cockpit, and assessed the situation. Although one flight attendant received minor injuries to her shoulder, there were no other injuries to any ground handling personnel, crew, the remaining two flight attendants, or the 56 passengers.

PERSONNEL INFORMATION

According to FAA records, the captain held an airline transport certificate with an airplane multiengine land rating. He held a first class medical certificate dated November 14, 2002, with no waivers or limitations noted. According to the Pilot/Operator Aircraft Accident Report (NTSB Form 6120.1/2), submitted by Delta Air Lines, the captain had a total flight time of 2,941 hours in all aircraft, 2,112 hours in this make and model, of which, 190 hours were in the last 90 days and 4 hours in the previous 24 hours.

According to FAA records, the first officer held an airline transport certificate with an airplane multiengine land rating. He held a first class medical certificate dated July 5, 2002, with no waivers or limitations noted. According to the 6120.1/2 submitted by Delta Air Lines, the first officer had a total flight time of 3,345 hours in all aircraft, 2,234 hours in this make and model, of which, 173 hours were in the last 90 days and 4 hours in the previous 24 hours.

AIRCRAFT INFORMATION

The airplane was a transport category, fixed wing, multiengine, 149 seat McDonnell Douglas MD-88. The airplane was manufactured by the McDonnell Douglas Aircraft Company in 1991 as serial number 53242. The airplane was equipped with two 19,000 lbs. Thrust, Pratt & Whitney (P&W) JT8D-219 turbofan engines. At the time of the accident, the airplane had accumulated a total of 33,331.5 flight hours, which included 26,221 cycles.


WRECKAGE AND IMPACT INFORMATION

The nose landing gear was rotated approximately 120 degrees left of center. The right front corner of the tug struck the left side of the airplane's fuselage approximately 6 feet aft of the main cabin door and approximately 4 feet below the cabin floor. The impact with the tug tore a hole approximately 4 feet by 2 feet in length along the left side of the fuselage, substantially damaging several station bulkheads.

TESTS AND RESEARCH

According to an NTSB Vehicle Recorders Division Engineer, on April 25, 2003, the airplane's flight data recorder (FDR), a Lockheed Model 209, s/n 4387, manufactured by Lockheed Aircraft Services, was examined. The recorder was in good condition, and the data was extracted normally from the recorder. This model 209 FDR records configuration data using an analog signal. The FDR records 64 words of digital information every second of relative time. Each second of recorded information is called a sub frame and is identified by a Sub frame Reference Number (SRN).

The data indicated that electrical power was restored to the FDR at SRN 46176. At SRN 46178, the data indicated that the left engine fuel flow increased from 328 pounds per hour (PPH) to 626 PPH. At SRN 46182, engine pressure ratio (EPR) for the left engine began increasing and N1 for left engine was at 10 percent. During this time, the right engine indicated holding with N1 at 0 percent, EPR at 1 and engine fuel flow unchanged at 109 PPH. Between SRN 46212 and 46216, longitudinal acceleration increased from -0.1 to 0.12 g, and then decreased to -0.31 g by SRN

 <p>National Transportation Safety Board FACTUAL REPORT AVIATION</p>	NTSB ID: DEN03FA070
	Occurrence Date: 04/22/2003
	Occurrence Type: Accident


Narrative (Continued)


46220. At SRN 46221, the left engine parameters continued increasing, the EPR was at its maximum of 2.09, and N1 had increased to 98 percent. The right engine EPR continued unchanged at 1, and N1 was at 10 percent. During these times, vertical acceleration reached a minimum of 0.95 g and a maximum of 1.06 g. At SRN 46226, the left engine parameters began decreasing and EPR was at 1.13, and N1 was 51 percent. Electrical power was then removed from the FDR.

ADDITIONAL INFORMATION

As outlined in MD-88 MEL 27-00-37, the procedures in step 11 identify that "either or both" engine throttles must be advanced to verify the operation of the slat takeoff warning horn. However, MD-88 MEL 27-00-37 does not include a step to retard the throttles.

Following this investigation, the maintenance procedures, as identified in MD-88 MEL 27-00-32, MD-88 MEL 27-00-36, MD-88 MEL 27-00-37, and similar procedures, as identified in MD-90 MEL 27-84-01, and MD-90 MEL 27-84-02, were revised with approval from Boeing. The MEL's now include a final step that states, "Return both throttles to idle and system controls to normal position."

 National Transportation Safety Board FACTUAL REPORT AVIATION		NTSB ID: DEN03FA070				
		Occurrence Date: 04/22/2003				
		Occurrence Type: Accident				
Landing Facility/Approach Information						
Airport Name Denver International		Airport ID: DEN	Airport Elevation 5431 Ft. MSL	Runway Used NA	Runway Length	Runway Width
Runway Surface Type: Unknown						
Runway Surface Condition: Unknown						
Type Instrument Approach: Unknown						
VFR Approach/Landing: Unknown						
Aircraft Information						
Aircraft Manufacturer McDonnell Douglas		Model/Series MD-88		Serial Number 53242		
Airworthiness Certificate(s): Transport						
Landing Gear Type: Retractable - Tricycle						
Homebuilt Aircraft? No		Number of Seats: 149	Certified Max Gross Wt. 149500 LBS		Number of Engines: 2	
Engine Type: Turbo Fan		Engine Manufacturer: Pratt & Whitney		Model/Series: JT8D219	Rated Power: 19000 LBS	
- Aircraft Inspection Information						
Type of Last Inspection Continuous Airworthiness		Date of Last Inspection 04/2003	Time Since Last Inspection 10.9 Hours		Airframe Total Time 33331.5 Hours	
- Emergency Locator Transmitter (ELT) Information						
ELT Installed? Yes		ELT Operated? No		ELT Aided in Locating Accident Site? No		
Owner/Operator Information						
Registered Aircraft Owner Wilmington Trust Co.		Street Address Rodney Square North				
		City Wilmington		State DE	Zip Code 19890	
Operator of Aircraft Same as Reg'd Aircraft Owner		Street Address Same as Reg'd Aircraft Owner				
		City		State	Zip Code	
Operator Does Business As: Delta Air Lines				Operator Designator Code: 026A		
- Type of U.S. Certificate(s) Held:						
Air Carrier Operating Certificate(s): Flag Carrier/Domestic						
Operating Certificate:			Operator Certificate:			
Regulation Flight Conducted Under: Part 121: Air Carrier						
Type of Flight Operation Conducted: Scheduled; Domestic; Passenger Only						
FACTUAL REPORT - AVIATION						

 <p>National Transportation Safety Board FACTUAL REPORT AVIATION</p>	NTSB ID: DEN03FA070
	Occurrence Date: 04/22/2003
	Occurrence Type: Accident

First Pilot Information

Name On File	City On File	State On File	Date of Birth On File	Age 48
-----------------	-----------------	------------------	--------------------------	-----------

Sex: M	Seat Occupied: Left	Principal Profession: Civilian Pilot	Certificate Number: On File
--------	---------------------	--------------------------------------	-----------------------------

Certificate(s): Airline Transport

Airplane Rating(s): Multi-engine Land

Rotorcraft/Glider/LTA: None

Instrument Rating(s): Airplane

Instructor Rating(s): None

Type Rating/Endorsement for Accident/Incident Aircraft? Yes	Current Biennial Flight Review? 08/2002
---	---

Medical Cert.: Class 1	Medical Cert. Status: Valid Medical--no waivers/lim.	Date of Last Medical Exam: 11/2002
------------------------	--	------------------------------------

- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Multi-Engine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	2941	2112								
Pilot In Command(PIC)										
Instructor										
Last 90 Days	190	190								
Last 30 Days										
Last 24 Hours	4	4								

Seatbelt Used? Yes	Shoulder Harness Used? Yes	Toxicology Performed? No	Second Pilot? Yes
--------------------	----------------------------	--------------------------	-------------------

Flight Plan/Itinerary

Type of Flight Plan Filed: IFR

Departure Point Same as Accident/Incident Location	State	Airport Identifier DEN	Departure Time 1245	Time Zone MDT
---	-------	---------------------------	------------------------	------------------

Destination Cincinnati	State OH	Airport Identifier LUK	
---------------------------	-------------	---------------------------	--


Type of Clearance: IFR

Type of Airspace: Class B

Weather Information

Source of Briefing: Company


Method of Briefing: Aircraft Radio; Telephone

 <p>National Transportation Safety Board FACTUAL REPORT AVIATION</p>	NTSB ID: DEN03FA070
	Occurrence Date: 04/22/2003
	Occurrence Type: Accident

Weather Information					
WOF ID	Observation Time	Time Zone	WOF Elevation	WOF Distance From Accident Site	Direction From Accident Site
DEN	1245	MDT	5431 Ft. MSL	NM	Deg. Mag.
Sky/Lowest Cloud Condition: Scattered			70 Ft. AGL	Condition of Light: Day	
Lowest Ceiling: Broken		150 Ft. AGL	Visibility: 10	SM	Altimeter: 29.75 "Hg
Temperature: 14 °C	Dew Point: 4 °C	Wind Direction: Variable		Density Altitude: 6747 Ft.	
Wind Speed: 3	Gusts:	Weather Conditions at Accident Site: Visual Conditions			
Visibility (RVR): Ft.	Visibility (RVV)	SM	Intensity of Precipitation:		
Restrictions to Visibility: None					
Type of Precipitation: None					

Accident Information		
Aircraft Damage: Substantial	Aircraft Fire: None	Aircraft Explosion: None

Classification: U.S. Registered/U.S. Soil					
- Injury Summary Matrix	Fatal	Serious	Minor	None	TOTAL
First Pilot				1	1
Second Pilot				1	1
Student Pilot					
Flight Instructor					
Check Pilot					
Flight Engineer					
Cabin Attendants			1	2	3
Other Crew					
Passengers				56	56
- TOTAL ABOARD -			1	60	61
Other Ground					
- GRAND TOTAL -			1	60	61

 <p>National Transportation Safety Board FACTUAL REPORT AVIATION</p>	NTSB ID: DEN03FA070
	Occurrence Date: 04/22/2003
	Occurrence Type: Accident

Administrative Information

Investigator-In-Charge (IIC)

Brannon D. Mayer

Additional Persons Participating in This Accident/Incident Investigation:

Jack Muldoon
Air Safety Investigator
Denver FSDO
26805 E. 68th Ave #200
Denver, CO 80249

T.R. Proven
Air Safety Investigator
FAA AAI-100
800 Independence Ave., S. W.
Washington, DC 20591

James W Reese
Fleet Captain
Delta Air Lines, Inc.
P.O. Box 20706
Atlanta, GA 30320

Peter S Frey
ALPA Affiliate
DAL Accident Investigation
6 Old Stadely Rough Road
Danbury, CT 06811